



AD03ZRR

report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Red
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg





Internet history

Entry 2

Date	2021-08-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-08-12
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #19	2022-04-04 16:49
MOT test number	309460111182
Result	✓ Passed
Next expiry date	2023-04-03
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18	2021-03-13 11:30
MOT test number	763002078474
Result	✓ Passed

MOT #17	2020-02-22 10:11
MOT test number	272396950896
Result	✓ Passed

MOT #16	2019-03-11 10:05
MOT test number	912241158575
Result	✓ Passed

MOT #15	2018-03-15 16:36
MOT test number	848219577258
Result	✓ Passed

MOT #14	2017-03-18 09:44
MOT test number	290511055033
Result	✓ Passed

**MOT #13** 2016-03-12 11:01**MOT test number** 761622906302**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #12** 2015-03-11 17:08**MOT test number** 166480775008**Result** ✓ Passed**MOT #11** 2015-03-11 15:34**MOT test number** 959920975050**Result** ✗ Failed**Fail** Nearside rear brake binding (3.7.B.1)**MOT #10** 2014-03-08 10:02**MOT test number** 319757564098**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9** 2013-03-21 17:08**MOT test number** 929110983011**Result** ✓ Passed**MOT #8** 2012-07-09 10:05**MOT test number** 309361992196**Result** ✓ Passed



MOT #7	2011-06-27 13:40
---------------	------------------

MOT test number	515028071122
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-06-27 12:03
---------------	------------------

MOT test number	319578071151
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Offside Front Anti-roll bar linkage insecure (2.4.G.1)
-------------	--

MOT #5	2010-07-20 10:26
---------------	------------------

MOT test number	452601300232
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-07-16 11:08
---------------	------------------

MOT test number	162807599140
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-07-16 11:13
---------------	------------------

MOT test number	831898898121
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-07-13 17:26
---------------	------------------

MOT test number	722424897102
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2006-07-11 12:10
---------------	------------------

MOT test number	141192896173
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	AD03ZRR
Plate since	2024-03-29
Current registration	AD03ZRR
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-07-25
Last registration	2022-04-04
Complete history	See info



Registration #1	2003-07-25	19 mi
Registration #2	2006-07-11	28.164 mi
Registration #3	2007-07-13	34.861 mi
Registration #4	2008-07-16	40.195 mi
Registration #5	2009-07-16	45.062 mi
Registration #6	2010-07-20	49.889 mi
Registration #7	2011-06-27	53.249 mi
Registration #8	2011-06-27	53.255 mi
Registration #9	2012-07-09	58.436 mi
Registration #10	2013-03-21	61.368 mi
Registration #11	2014-03-08	66.797 mi
Registration #12	2015-03-20	71.277 mi
Registration #13	2016-03-20	75.277 mi
Registration #14	2017-03-20	79.277 mi
Registration #15	2018-03-20	83.277 mi
Registration #16	2019-03-20	87.277 mi
Registration #17	2020-03-20	91.277 mi
Registration #18	2021-03-20	95.277 mi
Registration #19	2022-03-20	99.277 mi
Registration #20	2023-03-20	103.277 mi
Registration #21	2024-03-20	107.277 mi
Registration #22	2025-03-20	111.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	D4CB3590642