



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE EU4
Colour	Silver
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	209 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-14
Pictures	22
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2022-10-28
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	45
Total items failed	10

MOT #18 2021-10-29 12:39**MOT test number** 845809058539**Result** ✓ Passed**Next expiry date** 2022-10-28

- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #17 2021-10-28 11:48**MOT test number** 785804347565**Result** ✗ Failed

- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #16** 2020-09-29 11:28**MOT test number** 103897354651**Result** ✓ Passed**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Handbrake travel attention soon**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #15** 2019-04-25 15:33**MOT test number** 915866765544**Result** ✓ Passed**Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #14** 2018-04-27 11:22**MOT test number** 926587802951**Result** ✓ Passed**MOT #13** 2016-11-23 13:56**MOT test number** 420214334566**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front arm front inner bush (2.4.G.2)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #12**

2016-11-23 13:56

MOT test number

641557455473

Result**✗ Failed**

- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement front arm front inner bush (2.4.G.2)
- Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

MOT #11

2015-10-17 08:12

MOT test number

398152324474

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)

**MOT #10**

2015-10-14 10:57

MOT test number

787230914405

Result**✗ Failed****Fail**

Nearside rear parking brake recording little or no effort (3.7.B.6a)

Advice

Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

Advice

Nearside rear brake fluctuating, but not excessively (3.7.B.3)

Fail

Parking brake: efficiency below requirements (3.7.B.7)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Offside Front Brake hose slightly deteriorated (3.6.B.4d)

MOT #9

2014-09-17 10:53

MOT test number

357720164285

Result**✓ Passed****MOT #8**

2014-09-16 11:27

MOT test number

835119554281

Result**✗ Failed****Fail**

Parking brake: efficiency below requirements (3.7.B.7)

MOT #7

2013-09-04 09:19

MOT test number

278077043226

Result**✓ Passed****Notice**

Rear exhaust hanger broken

**MOT #6** 2012-09-04 15:36**MOT test number** 626748742271**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2012-09-04 15:36**MOT test number** 188628042261**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2011-09-13 16:42**MOT test number** 176096251201**Result** ✓ Passed**MOT #3** 2011-01-10 09:17**MOT test number** 905280411037**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #2	2011-01-10 09:17
MOT test number	225170811074
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Pass with rectification	Nearside Rear Upper Rear position lamp(s) not working (1.1.A.3b)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)

MOT #1	2009-11-27 09:40
MOT test number	563821939327
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 July 2022

✕
MOT

Expired:
28 October 2022

Tax status	Expired at 1 July 2022
Days left	668 days too late
MOT expiry date	28 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-05-17
Last registration	2021-10-29
Complete history	See info



Registration #1	2006-05-17	15 mi
Registration #2	2009-11-27	37.919 mi
Registration #3	2011-01-10	59.428 mi
Registration #4	2011-09-13	67.851 mi
Registration #5	2012-09-04	82.030 mi
Registration #6	2013-09-04	95.804 mi
Registration #7	2014-09-16	105.232 mi
Registration #8	2014-09-17	105.236 mi
Registration #9	2015-10-14	112.573 mi
Registration #10	2016-05-20	121.277 mi
Registration #11	2016-05-20	121.277 mi
Registration #12	2016-05-20	121.277 mi
Registration #13	2016-05-20	121.277 mi
Registration #14	2016-05-20	121.277 mi
Registration #15	2016-05-20	121.277 mi
Registration #16	2016-05-20	121.277 mi
Registration #17	2016-05-20	121.277 mi
Registration #18	2021-10-29	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2755 mm
Kerb weight	1611 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	394140