





General informationMakeTOYOTAModelHI-ACE 280 GS SWB P/V (88BHP)ColourBlackYear of manufacture2005Gearbox5 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	192 Nm at 1.200 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Diesel







Internet history

Entry 1

Date Pictures 2021-08-15

15

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-10
MOT pass rate	94 %
MOT passed	16
Failed MOT tests	1
Total advice items	29
Total items failed	2

MOT #17	2023-08-04 13:26	
MOT test number	970007858923	
Result	✓ Passed	
Next expiry date	2024-08-10	
Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Nearside & Offside (5.3.4 (a) (i))		
Advice Rear Gearbox mounting defective Differential		
Advice Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) ((i))	

867806196227
✓ Passed

MOT #15	2022-08-09 11:18
MOT test number	771209824732
Result	🗙 Failed
Fail Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))	

Fail Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))





MOT #14	2021-08-11 14:37	
MOT test number	703350473224	
Result	✓ Passed	
Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))		
Advice Rear Coil spring corroded both side (5.3.1 (b) (i))		

MOT #13		2020-10-14 07:56
MOT test	number	119466364325
Result		✓ Passed
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive	e movement (5.3.4
Advice	Rear diff , forward bush is worn	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing inner wall (5.2.3 (d) (ii)))
Advice (5.3.4 (a) (Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessi (i))	ve movement
Advice	Parts of the exhaust is starting to corrode	

MOT #12		2019-10-28 09:27
MOT test	number	529969615952
Result		✓ Passed
Advice (5.3.4 (a)	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in ex(i))	cessive movement
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords	s (5.2.3 (d) (i))
Advice	Rear diff front mounting poor condition	
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in exce	essive movement (5.3.4
Advice	Parts of exhaust corroded	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #11	2018-10-15 10:12
MOT test number	654553021869
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in exercise (5.3.4 (a) (i))	cessive movement
Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in exce (a) (i))	ssive movement (5.3.4

MOT #10	2017-10-10 08:48
MOT test number	518339680814
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
Advice Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	

MOT #9	2016-09-13 09:02
MOT test number	137875565010
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated movement (2.4.G.2)	d but not resulting in excessive

MOT #8	2015-09-11 07:57
MOT test number	666112783435
Result	✓ Passed
Advice Offside Front Anti-roll bar linkage rubber mounting deteriorated but no movement (2.4.G.2)	t resulting in excessive
Advice The rear axle diff, front bush is worn	
Advice Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice Nearside Rear tyre starting to crack	





MOT #7	2014-10-06 09:59
MOT test number	176889774272
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
MOT #6	2013-09-13 12:52
MOT test number	608526953202
Result	✓ Passed
MOT #5	2012-09-11 15:31
MOT test number	446515952203
Result	✓ Passed
MOT #4	2011-04-20 09:47
MOT test number	517900911160
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
MOT #3	2010-04-06 18:13
MOT test number	700636090016
Result	✓ Passed
MOT #2	2009-05-30 11:55
MOT test number	823050759139

Result

🗸 Passed






MOT #1		2008-09-01 08:58
MOT test	number	463465648280
Result		✓ Passed
Advice	Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	



Tax & MOT check







Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-09-02
Last registration	2023-08-04
Complete history	<u>See info</u>



Registration #1	2005-09-02	29 mi
Registration #2	2008-09-01	87.277 mi
Registration #3	2009-05-30	110.286 mi
Registration #4	2010-04-06	135.918 mi
Registration #5	2011-04-20	139.989 mi
Registration #6	2012-09-11	144.114 mi
Registration #7	2013-09-13	146.298 mi
Registration #8	2014-10-06	148.460 mi
Registration #9	2015-09-11	150.421 mi
Registration #10	2016-09-13	152.492 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.777 est
Registration #19		11.777 esi

More info \rightarrow





Car features

50225	Air conditioning
50295	
0482	
0501	
0566	
0567	
0569	

Additional information

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of seats	3
Engine number	2KD1316558