



TOYOTA

X8960HK

report date: 2024-03-29

General information

| | |
|---------------------|--------------------|
| Make | TOYOTA |
| Model | LANDCRUISER ESTATE |
| Colour | Green |
| Year of manufacture | 2000 |
| Gearbox | - |

Engine & fuel consumption

| | |
|-----------------|----------|
| Engine capacity | 3.378 cc |
| Fuel type | Petrol |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-26 |
| Pictures | 10 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-14 |
| MOT pass rate | 77 % |
| MOT passed | 17 |
| Failed MOT tests | 5 |
| Total advice items | 42 |
| Total items failed | 7 |

MOT #22 2024-02-14 14:56

MOT test number 957431966619

Result ✓ Passed

Next expiry date 2025-02-14

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Undertrays and covers fitted not allowing full inspection

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement all bush's (5.3.4 (a) (i))

MOT #21 2023-02-15 10:29

MOT test number 856070804950

Result ✓ Passed

Advice Offside Front Play in steering rack inner joint(s)

Advice Undertrays and covers fitted not allowing full inspection

Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2023-02-13 12:00

MOT test number

977479301157

Result**✗ Failed****Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Undertrays and covers fitted not allowing full inspection**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #19**

2022-02-14 16:10

MOT test number

112579406445

Result**✓ Passed****Advice** Offside Rear handbrake crank restricted movement**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view stone chipped (3.2 (a) (i))**MOT #18**

2022-02-01 08:32

MOT test number

405766024314

Result**✗ Failed****Minor** Windscreen damaged but not adversely affecting driver's view stone chipped (3.2 (a) (i))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear handbrake crank restricted movement**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2021-01-15 14:15**MOT test number** 327978351366**Result** ✓ Passed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Play in steering rack inner joint(s)**MOT #16** 2019-07-11 15:39**MOT test number** 607289259972**Result** ✓ Passed**Advice** Front Hydraulic leak, but not excessive steering rack gators damp (8.4.1 (a) (i))**MOT #15** 2019-07-11 11:11**MOT test number** 940563337442**Result** ✗ Failed**Advice** Front Hydraulic leak, but not excessive steering rack gators damp (8.4.1 (a) (i))**Fail** Offside Front Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))**MOT #14** 2018-07-17 15:13**MOT test number** 199719968405**Result** ✓ Passed**MOT #13** 2017-02-07 09:21**MOT test number** 451248770154**Result** ✓ Passed

**MOT #12**

2016-02-04 09:08

MOT test number

595709465806

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Shock absorber has a slightly worn bush (2.7.4)
- Advice** Vehicle tested when it is dirty

MOT #11

2015-02-04 15:27

MOT test number

325765235015

Result

✓ Passed

- Notice** Drivers side rear tyre has a nail in it.
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Notice** Under trays and heat shields obscuring vision of various components.
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Brake pipe slightly corroded (3.6.B.2c)

**MOT #10**

2015-02-02 10:47

MOT test number

349303635031

Result

✗ Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Drivers side rear tyre has a nail in it.**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Notice** Under trays and heat shields obscuring vision of various components.**MOT #9**

2014-02-03 09:10

MOT test number

838484334029

Result

✓ Passed

Advice Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Rear Fuel pipe slightly damaged (7.2.2)**MOT #8**

2013-01-28 11:52

MOT test number

517448923050

Result

✓ Passed

Advice Offside Front Upper Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Upper Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Exhaust joints rusty**MOT #7**

2012-01-30 13:20

MOT test number

607790032080

Result

✓ Passed

**MOT #6** 2012-01-30 11:45**MOT test number** 756470032055**Result** ✗ Failed**Fail** Brake load sensing valve seized (3.6.E.3)**MOT #5** 2011-02-10 15:39**MOT test number** 195411041017**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Shock absorber has a slightly worn bush (2.7.4)**MOT #4** 2010-01-26 15:41**MOT test number** 602506020056**Result** ✓ Passed**MOT #3** 2009-01-28 16:19**MOT test number** 563048229063**Result** ✓ Passed**MOT #2** 2008-02-12 13:50**MOT test number** 620783448073**Result** ✓ Passed**MOT #1** 2006-09-13 13:31**MOT test number** 302416156286**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
14 February 2025

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 August |
| Days left | | 95 |
| MOT expiry date | | 14 February 2025 |
| Full MOT history | | See MOT history |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | X896 OHK |
| Plate since | 2019-03-29 |
| Current registration | X896 OHK |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2000-09-13 |
| Last registration | 2024-02-14 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2000-09-13 | 15 mi |
| Registration #2 | 2006-09-13 | 95.612 mi |
| Registration #3 | 2008-02-12 | 110.205 mi |
| Registration #4 | 2009-01-28 | 112.879 mi |
| Registration #5 | 2010-01-26 | 115.997 mi |
| Registration #6 | 2011-02-10 | 119.447 mi |
| Registration #7 | 2012-01-30 | 122.268 mi |
| Registration #8 | 2012-01-30 | 122.270 mi |
| Registration #9 | 2013-01-28 | 125.509 mi |
| Registration #10 | 2014-02-03 | 128.978 mi |
| Registration #11 | 2015-02-02 | 134.421 mi |
| Registration #12 | 2015-02-04 | 134.440 mi |
| Registration #13 | 2015-05-20 | 135.377 mi |
| Registration #14 | 2015-05-20 | 135.377 mi |
| Registration #15 | 2015-05-20 | 135.377 mi |
| Registration #16 | 2015-05-20 | 135.377 mi |
| Registration #17 | 2015-05-20 | 135.377 mi |
| Registration #18 | 2015-05-20 | 135.377 mi |
| Registration #19 | 2015-05-20 | 135.377 mi |
| Registration #20 | 2015-05-20 | 135.377 mi |
| Registration #21 | 2015-05-20 | 135.377 mi |
| Registration #22 | 2015-05-20 | 135.377 mi |
| Registration #23 | 2015-05-20 | 135.377 mi |
| Registration #24 | 2015-05-20 | 135.377 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Additional information

| | |
|-----------------|-------------|
| Number of seats | 8 |
| Engine number | SVZ01027374 |