





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 CACTUS BLUEHDI FLAIR S/S
Colour	White
Year of manufacture	2017
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	88.3 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	А



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 5

Date 2022-11-15

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

Entry 4

Date 2022-08-26

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

Date 2022-07-28

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Pictures 32

Listing price View report CarCheck.co.uk Page 2/11










source: autotrader.co.uk

Entry 1

Date	2021-07-03
Pictures	5
Listing price	View report









source: cargurus.co.uk



report date: 2024-03-28

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-26
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #7	2024-01-22 16:59
MOT test number	859855241311
Result	✓ Passed
Next expiry date	2025-01-26
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps (i))	or light sources (4.7.1 (b)

MOT #6	2023-01-27 15:44
MOT test number	439804263681
Result	✓ Passed

MOT #5		2022-07-11 08:57
MOT test	number	296929337938
Result		✓ Passed
Advice	Coolant low	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Handbrake lever has some travel	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2021-07-12 19:13

MOT test number 185427336913

Result
✓ Passed

MOT #3 2021-07-08 15:28

MOT test number 568535746218

Result × Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #2 2020-06-30 12:56

MOT test number 872192484490

Result \rightarrow Passed

MOT #1 2020-06-23 11:58

MOT test number 350064771061

Result \rightarrow Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	26 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

YM1700W

report date: 2024-03-28

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	SIE AIS UK
Plate since	
Current registration	NE NE
Plade since	

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-06-30
Last registration	2024-01-22
Complete history	See info



Registration #1	2017-06-30	7 mi
Registration #2	2020-06-30	25.503 mi
Registration #3		11.777 es
Registration #4	2021-07-08	31.505 mi
Registration #5	2021-07-12	31.506 mi
Registration #6		11.777 es
Registration #7		0.074
Registration #8		11.777 ea
Registration #9		D.777 ea
Registration #10		71,777 66
Registration #11		0.074
Registration #12		11.777 es

More info >


CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	59%
Safety systems	58%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1474 mm
Length	3996 mm
Wheel base	2540 mm
Kerb weight	1090 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHA3268023

CarCheck.co.uk page 11/11