



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC TDCI 125
Colour	Black
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-20
Pictures	29
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-20
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	55
Total items failed	14

MOT #16 2023-08-21 08:48

MOT test number 892290273655

Result ✓ Passed

Next expiry date 2024-08-20

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15 2022-08-20 08:29

MOT test number 472656355287

Result ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14** 2022-08-20 08:29**MOT test number** 850898557252**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #13** 2021-08-17 10:01**MOT test number** 491132232362**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2020-08-13 17:07**MOT test number** 937424980480**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Rear Suspension rod pin or bush worn but not resulting in excessive movement bothside (5.3.4 (a) (i))**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11**

2020-08-13 10:14

**MOT test number**

141091525532

**Result**

✗ Failed

- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Suspension rod pin or bush worn but not resulting in excessive movement bothside (5.3.4 (a) (i))
- Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))
- Advice** Rear Coil spring corroded bothside (5.3.1 (b) (i))

**MOT #10**

2019-08-15 14:56

**MOT test number**

994156398497

**Result**

✓ Passed

- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9**

2019-08-14 11:34

**MOT test number**

515407550374

**Result**

✗ Failed

- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Rear Direction indicator incorrect colour both sides (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8**

2018-08-18 11:06

**MOT test number**

615628201199

**Result**

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear All direction indicators slightly discoloured (4.4.3 (a))

**MOT #7** 2018-08-16 10:28**MOT test number** 955702621036**Result** ✗ Failed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Front Headlamp aim too high both sides (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Front Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #6** 2017-08-16 13:42**MOT test number** 198882764944**Result** ✓ Passed**MOT #5** 2016-08-04 11:09**MOT test number** 648429604186**Result** ✓ Passed

**MOT #4** 2015-08-20 11:47**MOT test number** 328642435469**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #3** 2014-09-22 12:24**MOT test number** 496415664247**Result** ✓ Passed

- Notice** Undertrays fitted
- Notice** Windscreen chipped
- Notice** Front brake discs corroded and worn

**MOT #2** 2014-09-22 10:32**MOT test number** 986035164226**Result** ✗ Failed

- Notice** Both rear tyres heavily worn out of shape on inner edges
- Notice** Windscreen chipped
- Notice** Front brake discs corroded and worn
- Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)
- Notice** Undertrays fitted

**MOT #1** 2013-09-13 12:37**MOT test number** 868576753263**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
20 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	20 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>WV600EO</b>
Plate since	2019-03-28
Current registration	<b>WV600EO</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-30
Last registration	2023-08-21
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	20 mi
Registration #2	2013-09-13	49.538 mi
Registration #3	2014-09-22	61.684 mi
Registration #4	2014-09-22	61.684 mi
Registration #5	2015-08-20	72.764 mi
Registration #6	2016-08-04	81.048 mi
Registration #7	2017-08-16	87.702 mi
Registration #8	2018-08-16	94.545 mi
Registration #9	2018-08-18	94.546 mi
Registration #10	2019-08-18	94.546 mi
Registration #11	2019-08-18	94.546 mi
Registration #12	2019-08-18	94.546 mi
Registration #13	2019-08-18	94.546 mi
Registration #14	2019-08-18	94.546 mi
Registration #15	2019-08-18	94.546 mi
Registration #16	2019-08-18	94.546 mi
Registration #17	2019-08-18	94.546 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	AP49377