





report date: 2024-03-28

General information

| Make | BMW |
|---------------------|-------------------|
| Model | X6 M50D |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.3 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 376 BHP |
|-------------------------|---------------------|
| Max. torque | 740 Nm at 2.000 rpm |
| Engine capacity | 2.993 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 205 g/km |
| CO2 label | K |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-06-10

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-07-02 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 13 |
| Total items failed | 0 |

| MOT #5 | 2023-07-03 12:15 |
|------------------|------------------|
| MOT test number | 927118652243 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-02 |

| MOT #4 | | 2023-06-26 08:14 |
|----------|--|------------------|
| MOT test | number | 338168492374 |
| Result | | X Failed |
| MAJOR | Offside Side repeater not working (4.4.1 (a) (ii)) | |

| MOT #3 | | 2022-06-21 11:27 |
|----------|--|----------------------|
| MOT test | number | 196392021988 |
| Result | | ✓ Passed |
| Minor | Offside Front Window excessively tinted but not adversely affecting driver's v | view (3.2 (b) (i)) |
| Advice | Items removed from driver's view prior to test | |
| Minor | Nearside Front Window excessively tinted but not adversely affecting driver's | s view (3.2 (b) (i)) |
| Minor | Windscreen excessively tinted but not adversely affecting driver's view (3.2 (| (b) (i)) |

CarCheck.co.uk page 3/11



MOT #2 2022-06-20 09:22

MOT test number 965251335283

Result X Failed

DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Offside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Nearside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))

Advice Items removed from driver's view prior to test

Minor Windscreen excessively tinted but not adversely affecting driver's view (3.2 (b) (i))

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #1 2021-06-28 10:44

MOT test number 167297583022

Result
✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 216 |
| MOT expiry date | 2 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|--------------|
| Band | K |
| First licence fee (12 months) | £ 1.565,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 2.220,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report | | ve? |
|---|-------------------|------|
| | | |
| | | |
| | | |
| *************************************** | | |
| | | |
| | | |
| | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this BMW had different number plates. | | |
| Number of plates | | |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | NIEZ AIS UK | |
| Flate since | | 0.00 |
| | More info | > |

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact into

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-06-18 |
| Last registration | 2023-07-03 |
| Complete history | See info |



| Registration #1 | 2018-06-18 | 22 mi |
|-----------------|------------|-----------|
| Registration #2 | | 0.074 |
| Registration #3 | 2021-06-28 | 9.848 mi |
| Registration #4 | 2022-06-20 | 26.168 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.177 es |

More info >

CarCheck.co.uk page 10/11



Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1938 mm |
|---------------------|---------|
| Height | 1762 mm |
| Length | 4886 mm |
| Wheel base | 2933 mm |
| Kerb weight | 2190 kg |
| Max. allowed weight | 3080 kg |

Additional information

| Fuel tank capacity | 85 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/1 |

Number of axles 2

Engine number 90531947