



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 ALLURE COUPE CABRIOLET
Colour	Red
Year of manufacture	2008
Top speed	119 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-06-25
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-10
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	44
Total items failed	20

MOT #22	2023-07-11 13:19
MOT test number	344908340717
Result	✓ Passed
Next expiry date	2024-07-10
Advice	Lower engine mount slight play

MOT #21	2023-07-04 15:00
MOT test number	991428986592
Result	✗ Failed
Minor	Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
Fail	Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Cv boot insecure (6.1.7 (g) (ii))
Advice	Lower engine mount slight play

**MOT #20**

2022-06-28 13:39

MOT test number

569915473630

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**MOT #19**

2022-06-21 13:54

MOT test number

238145904190

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #18**

2021-06-29 08:39

MOT test number

555743823684

Result

✓ Passed

MOT #17

2020-11-30 13:09

MOT test number

921969163743

Result

✓ Passed

**MOT #16** 2020-11-30 13:09**MOT test number** 691921921635**Result** ✗ Failed

- Pass with rectification** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #15 2019-12-03 09:54**MOT test number** 466680722009**Result** ✓ Passed

- Advice** Nearside front tyre worn badly on edges [near to exposing chords]recommend early renewal 205/55r16 91v
- Advice** Middle 2x exhaust brackets corroded /broken recommend early repair

MOT #14 2018-12-10 13:51**MOT test number** 953702366166**Result** ✓ Passed

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Service brake binding but not excessively both front (1.2.1 (f))
- Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #13**

2018-12-10 13:51

MOT test number

836512983720

Result**✗ Failed**

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Service brake binding but not excessively both front (1.2.1 (f))
- Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #12

2017-12-11 11:31

MOT test number

517804267613

Result**✓ Passed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #11**

2017-12-11 11:31

MOT test number

447899466788

Result**✗ Failed****Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10**

2016-10-15 08:54

MOT test number

245538113835

Result**✓ Passed****Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Tyre worn close to the legal limit both front (4.1.E.1)**MOT #9**

2015-10-19 10:20

MOT test number

846525585956

Result**✓ Passed****MOT #8**

2015-10-19 10:20

MOT test number

402451181411

Result**✗ Failed****Pass with rectification** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #7** 2014-09-12 09:06**MOT test number** 188845454229**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-07-16 16:52**MOT test number** 737487893152**Result** ✓ Passed**Notice** Nearside rear brake pads very low and brake slightly binding**Notice** Inner edge wear on front tyres**MOT #5** 2013-07-16 16:52**MOT test number** 579477793123**Result** ✗ Failed**Notice** Nearside rear brake pads very low and brake slightly binding**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Inner edge wear on front tyres**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2012-06-28 15:38**MOT test number** 256560182467**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2012-06-28 11:59**MOT test number** 146380582182**Result** ✗ Failed**Fail** Offside Front Mechanical brake component has restricted free movement (3.5.1k)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-07-26 14:52**MOT test number** 825537801225**Result** ✓ Passed**MOT #1** 2011-07-08 15:07**MOT test number** 246159281167**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 July 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-06-30
Last registration	2023-07-11
Complete history	See info



Registration #1	2008-06-30	17 mi
Registration #2	2011-07-08	22.336 mi
Registration #3	2011-07-26	22.337 mi
Registration #4	2012-06-28	29.658 mi
Registration #5	2012-06-28	29.658 mi
Registration #6	2013-07-16	38.900 mi
Registration #7	2014-09-12	44.584 mi
Registration #8	2015-10-19	50.992 mi
Registration #9	2015-10-19	50.992 mi
Registration #10	2016-10-15	55.669 mi
Registration #11	2017-12-11	60.460 mi
Registration #12	2017-12-11	60.460 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi
Registration #17	2019-06-20	75.377 mi
Registration #18	2019-06-20	75.377 mi
Registration #19	2019-06-20	75.377 mi
Registration #20	2019-06-20	75.377 mi
Registration #21	2019-06-20	75.377 mi
Registration #22	2019-06-20	75.377 mi
Registration #23	2019-06-20	75.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1528 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	FX7U3309544