



MF60LKZ

report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC 110
Colour	Silver
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	115 g/km
CO2 label	C





MOT history

MOT expiry date	2023-09-16
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	35
Total items failed	0

MOT #13 2022-09-06 15:13

MOT test number 960601086697

Result ✓ Passed

Next expiry date 2023-09-16

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Engine covers and under trays are fitted below vehicle
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12 2021-09-08 10:30

MOT test number 885400413739

Result ✓ Passed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2020-09-17 08:28**MOT test number** 809424240537**Result** ✓ Passed

- Advice** Rear tyres cracked on sidewalls
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2020-09-12 08:22**MOT test number** 706260364224**Result** ✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear tyres cracked on sidewalls
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #9 2019-09-09 09:13**MOT test number** 519232053347**Result** ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside mirror damaged
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear tyre age cracked

**MOT #8** 2018-09-10 11:59**MOT test number** 919729834251**Result** ✓ Passed

- Advice** Rear tyres cracked on sidewalls
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front tyre worn slightly on inner edge
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn very low on inner edge (5.2.3 (e))

MOT #7 2018-09-10 11:41**MOT test number** 462922373176**Result** ✗ Failed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear tyres cracked on sidewalls
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn very low on inner edge (5.2.3 (e))
- MAJOR** Nearside Headlamp are incorrectly positioned bulb insecure (4.1.4 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front tyre worn slightly on inner edge
- Advice** Items removed from driver's view prior to test

MOT #6 2017-09-08 13:37**MOT test number** 174747794868**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

**MOT #5** 2016-08-26 11:26**MOT test number** 141991953394**Result** ✓ Passed**MOT #4** 2015-09-09 09:26**MOT test number** 348768295145**Result** ✓ Passed**Advice** Engine cover and undertrays fitted not allowing full inspection**MOT #3** 2014-08-18 14:37**MOT test number** 296980434238**Result** ✓ Passed**MOT #2** 2014-04-08 16:38**MOT test number** 549998994053**Result** ✓ Passed**MOT #1** 2013-08-14 11:45**MOT test number** 469666523225**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
29 February 2024

✕
MOT

Expired:
16 September 2023

Tax status	Expired at 29 February 2024
Days left	60 days too late
MOT expiry date	16 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	MF60LKZ
Plate since	2024-03-29
Current registration	MF60LKZ
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-09-13
Last registration	2022-09-06
Complete history	See info



Registration #1	2010-09-13	16 mi
Registration #2	2013-08-14	33.831 mi
Registration #3	2014-04-08	35.814 mi
Registration #4	2014-08-18	38.395 mi
Registration #5	2015-09-09	40.556 mi
Registration #6	2016-08-26	47.366 mi
Registration #7	2017-09-08	56.139 mi
Registration #8	2018-09-08	65.277 mi
Registration #9	2019-09-08	74.415 mi
Registration #10	2020-09-08	83.553 mi
Registration #11	2021-09-08	92.691 mi
Registration #12	2022-09-06	101.829 mi
Registration #13	2023-09-06	110.967 mi
Registration #14	2024-03-29	120.105 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AU23426