





General information

Make	PEUGEOT
Model	307 X-LINE
Colour	Silver
Year of manufacture	2005
Top speed	107 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	133 Nm at 3.250 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry	1

Date Pictures 2021-10-19

11

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-05
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	32
Total items failed	6

MOT #23		2023-11-06 09:31
MOT test	number	871627319945
Result		✓ Passed
Next expi	ry date	2024-11-05
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Areas of vehicle underside have surface corrosion.	
Advice	Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside front brake pipe nut corroded.	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))



		report date: 2024-03-28
MOT #22		2023-11-06 09:31
MOT test number		641411656729
Result		🗙 Failed
Advice Areas of vehicle	underside have surface corrosion.	
Pass with rectification prevents the ingress of dirt	Offside Drive shaft joint constant velocity boot sp (6.1.7 (g) (ii))	lit or insecure, no longer
Advice Offside Rear Bra	ake disc worn, pitted or scored, but not seriously we	eakened (1.1.14 (a) (ii))
Advice Offside Front Se	rvice brake binding but not excessively (1.2.1 (f))	
Advice Offside front bra	ake pipe nut corroded.	

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #21		2022-10-13 13:19
MOT test	number	530606774013
Result		✓ Passed
Advice	Engine oil leak	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front head lamp lenses fading	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

VD55PRE





MOT #20		2022-10-12 12:32
MOT test	number	178177784413
Result		🗙 Failed
DANGER	OUS Offside Front Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Front head lamp lenses fading	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Engine oil leak	

MOT #19	2021-08-23 14:09
MOT test number	114348383492
Result	✓ Passed

MOT #18	2021-08-23 09:52
MOT test number	869853615506
Result	🗙 Failed
MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b)) (i))

MOT #17	2020-09-03 09:10
MOT test number	775551980997
Result	✓ Passed

MOT #16	2019-09-03 10:29
MOT test number	501539882843
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #15		2018-08-29 13:35
MOT test	number	725802667795
Result		✓ Passed
MOT #14		2018-08-29 09:43
MOT test	number	828996381763
Result		🗙 Failed
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
MOT #13		2017-08-21 10:50
MOT test	number	560249226820
Result		✓ Passed
MOT #12		2016-08-17 11:08
MOT test	number	200874173343
Result		✓ Passed
Advice (2.4.G.2)	Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventir	ng the ingress of dirt
Advice	Offside Rear brake binding	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #11	2015-08-27 15:02
MOT test number	425618780520
Result	✓ Passed

MOT #10	2015-08-27 09:24
MOT test number	941533608379
Result	🗙 Failed
Fail Offside Front coil spring broken (2.4.C.1a)	





MOT #9	2014-08-22 10:21
MOT test number	485114334212
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #8	2013-08-23 14:51
MOT test number	515775033291
Result	🗸 Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #7	2013-08-23 10:44
MOT test number	425215633209
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

FailNearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

FailNearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #6	2012-08-23 11:13
MOT test number	639746932218
Result	✓ Passed

MOT #5	2011-08-30 13:29
MOT test number	235182641213
Result	✓ Passed

MOT #4	2010-08-24 10:09
MOT test number	403856030298
Result	✓ Passed





MOT #3		2009-08-24 11:31
MOT test number		481456739229
Result		✓ Passed
MOT #2		2008-08-14 11:51
MOT test number		170527728290
Result		✓ Passed
MOT #1		2008-08-14 11:51
MOT test number		392627728419
Result		🗙 Failed
Pass with rectification N	earside Headlamp aim too low (1.8)	



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 February 2025	5 November 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 November 2024
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and and a second s	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-12
Last registration	2023-11-06
Complete history	See info



Registration #1	2005-09-12	7 mi
Registration #2	2008-08-14	15.411 mi
Registration #3	2009-08-24	21.750 mi
Registration #4	2010-08-24	27.892 mi
Registration #5	2011-08-30	31.456 mi
Registration #6	2012-08-23	36.174 mi
Registration #7	2013-08-23	39.691 mi
Registration #8	2013-08-23	39.692 mi
Registration #9	2014-08-22	43.228 mi
Registration #10	2015-08-27	46.458 mi
Registration #11	2015-08-27	46.459 mi
Registration #12	2016-08-17	49.718 mi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		
Registration #16		11.777 est
Registration #16 Registration #17		11.777 est 11.777 est
		0.707 est 0.707 est 0.707 est
Registration #17		0.707 es 0.707 es 0.707 es 0.707 es
Registration #17 Registration #18		0.202 es
Registration #17 Registration #18 Registration #19		0.777 est 0.777 est 0.777 est 0.777 est 0.777 est 0.777 est
Registration #17 Registration #18 Registration #19 Registration #20		11.777 44 11.777 44 11.777 44 11.777 44 11.777 44 11.777 44 11.777 44
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

***** see crash video



Dimensions & weight	
Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1170 kg
Max. allowed weight	1639 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of seats CarCheck.co.uk

Number of axles	2
Engine number	FE010159010