





report date: 2024-03-29

General information

Make	FIAT
Model	500 L TWINAIR PLUS
Colour	Purple
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-16
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	9
Total items failed	11

MOT #12	2023-11-17 07:44
MOT test number	848265187571
Result	✓ Passed
Next expiry date	2024-11-16

MOT #11	2023-11-16 08:19
MOT test number	708863552806
Result	× Failed
Advice Rear Brakes imbalanced requirements only just met. It would appear that the brequires adjustment or repair. (1.2.1 (b) (i))	oraking system
Fail Nearside Front Macpherson strut pin or bush excessively worn strut top bush (5.3.	4 (a) (i))
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1	. (b) (ii))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail Nearside Front Service brake excessively binding (1.2.1 (f))	
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #10	2021-02-05 11:26
MOT test number	916986311884
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #8

MOT test number

274245826536

Result

MOT #7

2018-10-22 10:05

MOT test number

150725193980

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #5

MOT test number

364465167165

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



MOT #4 2017-10-19 09:28

MOT test number 911558647518

Result X Failed

Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Registration plate lamp not working (1.1.C.1d)

Fail Offside Front Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)

MOT #3 2016-10-13 09:53

MOT test number 137491998014

Result ✓ Passed

MOT #2 2015-07-01 16:56

MOT test number 555742185169

Result ✓ Passed

MOT #1 2015-06-30 16:28

MOT test number 405031985160

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 16 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

o mile motory	
For how long did the current and previous owner(s) have this FIAT? How many owners did check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
See in this check if this HAT had different humber plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	OK ON THE STATE OF
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-08-08
Last registration	2023-11-17
Complete history	See info



Registration #1	2012-08-08	19 mi
Registration #2	2015-06-30	21.459 mi
Registration #3	2015-07-01	21.459 mi
Registration #4	2016-10-13	28.652 mi
Registration #5	2017-10-19	34.744 mi
Registration #6	2017-10-20	34.746 mi
Registration #7	2018-10-19	41.034 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 0054800