



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	White
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-28
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-01
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	31
Total items failed	3

MOT #14	2024-04-02 09:41
MOT test number	952068088798
Result	✓ Passed
Next expiry date	2025-04-01
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #13	2023-03-21 16:58
MOT test number	848077478610
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #12**

2023-03-21 12:29

MOT test number

526413516339

Result**✗ Failed**

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Fluid leak, but not excessive Coolant leaking from coolant tank (8.4.1 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11

2022-03-26 10:30

MOT test number

615627003808

Result**✓ Passed**

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #10

2021-03-30 13:21

MOT test number

347818608399

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2021-03-30 09:50**MOT test number** 878856487393**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Front Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Central Exhaust system insecure (6.1.2 (a))**MOT #8** 2020-03-23 13:32**MOT test number** 670128665838**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-03-23 13:32**MOT test number** 876163684571**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Items removed from driver's view prior to test**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #6** 2019-03-25 16:37**MOT test number** 900634254856**Result** ✓ Passed**Advice** Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**MOT #5** 2018-03-28 14:12**MOT test number** 695915583632**Result** ✓ Passed**MOT #4** 2017-03-31 08:03**MOT test number** 226654093784**Result** ✓ Passed**Advice** Nearside Rear Tyre cracking on outer sidewall**Advice** Offside Rear Tyre cracking on outer sidewall**MOT #3** 2016-03-18 11:50**MOT test number** 365212591275**Result** ✓ Passed**MOT #2** 2016-03-18 08:41**MOT test number** 786491309960**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported exhaust hanger corroded away (7.1.1)**MOT #1** 2015-02-28 10:41**MOT test number** 495529855064**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
1 April 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	1 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-01
Last registration	2024-04-02
Complete history	See info



Registration #1	2012-03-01	6 mi
Registration #2	2015-02-28	20.524 mi
Registration #3	2016-03-18	31.386 mi
Registration #4	2016-03-18	31.386 mi
Registration #5	2017-03-31	40.345 mi
Registration #6	2018-03-28	49.277 mi
Registration #7	2019-03-25	57.532 mi
Registration #8	2020-03-23	64.623 mi
Registration #9	2020-03-23	64.623 mi
Registration #10	2020-03-23	64.623 mi
Registration #11	2020-03-23	64.623 mi
Registration #12	2020-03-23	64.623 mi
Registration #13	2020-03-23	64.623 mi
Registration #14	2020-03-23	64.623 mi
Registration #15	2020-03-23	64.623 mi
Registration #16	2020-03-23	64.623 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA1665093