



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV4 D-4D T180
Colour	Green
Year of manufacture	2008
Top speed	124 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2



Date	2021-12-11
Pictures	18
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-09
Pictures	28
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-03
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	32
Total items failed	2

MOT #15 2023-05-04 14:20

MOT test number 315299378728

Result ✓ Passed

Next expiry date 2024-06-03

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Central Rear Passenger seat(s) missing at time of test

Advice Nearside Rear Passenger seat(s) missing at time of test

MOT #14 2023-05-04 11:34

MOT test number 429990404753

Result ✗ Failed

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

DANGEROUS Nearside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))

MAJOR Front Sound deadening material insecure bonnet (8.1.1 (b) (i))

Advice Central Rear Passenger seat(s) missing at time of test

Pass with rectification Nearside Front Headlamp aim too far to the right (4.1.2 (a))

DANGEROUS Offside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))

Advice Nearside Rear Passenger seat(s) missing at time of test

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13** 2022-05-12 12:43**MOT test number** 508737171014**Result** ✓ Passed**MOT #12** 2022-05-12 12:43**MOT test number** 973028621185**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2021-06-04 14:46**MOT test number** 650385505742**Result** ✓ Passed**MOT #10** 2020-08-12 10:03**MOT test number** 493911925689**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2019-08-12 08:29**MOT test number** 186460094875**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-08-13 08:19**MOT test number** 121604993751**Result** ✓ Passed**MOT #7** 2017-08-11 10:45**MOT test number** 299426279765**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2016-08-11 08:49**MOT test number** 608703699208**Result** ✓ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2015-08-14 09:49**MOT test number** 686566125245**Result** ✓ Passed

- Notice** Front brake discs heavily corroded and pitted on inner face
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Rear brake discs corroded

**MOT #4** 2014-09-24 13:33**MOT test number** 366967964231**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-09-04 10:32**MOT test number** 209467143228**Result** ✓ Passed**Notice** All four tyres cracked around the side walls**Notice** Oil leak**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2012-09-05 14:33**MOT test number** 388189842469**Result** ✓ Passed**MOT #1** 2011-09-19 15:02**MOT test number** 165722661228**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
3 June 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	3 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-24
Last registration	2023-05-04
Complete history	See info



Registration #1	2008-09-24	13 mi
Registration #2	2011-09-19	7.229 mi
Registration #3	2012-09-05	9.253 mi
Registration #4	2013-09-04	12.352 mi
Registration #5	2014-09-24	19.236 mi
Registration #6	2015-08-14	30.025 mi
Registration #7	2016-08-11	43.576 mi
Registration #8	2017-08-11	54.794 mi
Registration #9	2018-08-13	71.742 mi
Registration #10	2019-05-20	95.377 mi
Registration #11	2020-05-20	121.377 mi
Registration #12	2021-05-20	151.377 mi
Registration #13	2022-05-20	181.377 mi
Registration #14	2023-05-20	211.377 mi
Registration #15	2024-05-20	241.377 mi
Registration #16	2025-05-20	271.377 mi
Registration #17	2026-05-20	301.377 mi
Registration #18	2027-05-20	331.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1595 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0235441