



report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Black
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-02-07
Pictures	16
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2025-02-10
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	25
Total items failed	6

MOT #10	2024-02-02 17:32
MOT test number	368073778773
Result	✓ Passed
Next expiry date	2025-02-10
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Offside Rear reflector defective or damaged by up to 50% of the reflecting surface Paint overspray. (4.8.1 (a) (i))
Advice	Coil spring corroded Both sides rear. (5.3.1 (b) (i))
Advice	Exhaust emissions higher than average for this type of vehicle. Only meets requirements due to the output fluctuating.

**MOT #9** 2024-02-02 15:10**MOT test number** 145164545407**Result** ✗ Failed**Advice** Coil spring corroded Both sides rear. (5.3.1 (b) (i))**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Exhaust emissions higher than average for this type of vehicle. Only meets requirements due to the output fluctuating.**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface Paint overspray. (4.8.1 (a) (i))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #8** 2023-02-01 15:55**MOT test number** 564706857017**Result** ✓ Passed**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7**

2023-02-01 10:03

**MOT test number**

540776253410

**Result****✗ Failed****Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp aim too low and too far to the right. (4.1.2 (a))**Advice** Offside rear door stiff to open on sliding mechanism..**Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface Paint overspray. (4.8.1 (a) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush bonding failed. (5.3.4 (a) (i))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Nearside rear tyre has a screw in the tread.**MOT #6**

2022-02-02 09:39

**MOT test number**

292889251158

**Result****✓ Passed****Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #5**

2021-02-11 10:59

**MOT test number**

345687468562

**Result****✓ Passed****MOT #4**

2020-03-04 14:34

**MOT test number**

594025785766

**Result****✓ Passed**

**MOT #3** 2019-03-14 10:01**MOT test number** 821114959516**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2018-03-22 12:16**MOT test number** 355027927185**Result** ✓ Passed**MOT #1** 2017-03-20 12:48**MOT test number** 395611867282**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
10 February 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	10 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>SK14DHM</b>
Plate since	2019-03-28
Current registration	<b>SK14DHM</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2014-03-31	15 mi
Registration #2	2017-03-20	12.701 mi
Registration #3	2018-03-22	24.959 mi
Registration #4	2019-03-14	37.839 mi
Registration #5	2020-03-04	50.312 mi
Registration #6	2020-03-20	55.277 mi
Registration #7	2020-03-20	55.277 mi
Registration #8	2020-03-20	55.277 mi
Registration #9	2020-03-20	55.277 mi
Registration #10	2020-03-20	55.277 mi
Registration #11	2020-03-20	55.277 mi
Registration #12	2020-03-20	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	ES23713