





report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Black
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2022-01-17

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2022-01-16

 Pictures
 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-26
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	11
Total items failed	7

MOT #15	2024-02-27 11:39
MOT test number	744873628568
Result	✓ Passed
Next expiry date	2025-02-26
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #14		2022-10-01 08:54
MOT test	number	843605900241
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #13	2021-10-08 07:05
MOT test number	879987102744
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #12 2021-10-07 12:27

MOT test number 471017795788

Result X Failed

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-10-14 14:33

MOT test number 922877792531

Result
✓ Passed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10 2020-10-08 11:56

MOT test number 337801637598

Result ★ Failed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Rear Tyre has a tear, caused by separation or partial failure of its structure BOTH REAR.(185/60/15) (5.2.3 (d) (ii))

Fail Offside Front Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #9 2019-10-05 09:15

MOT test number 867097460762

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #8	2018-10-12 14:42
MOT test number	680028809601
Result	✓ Passed
MOT #7	2018-03-19 13:46
MOT test number	917111927826
Result	✓ Passed
MOT #6	2017-03-16 15:40
MOT test number	351415871225
Result	✓ Passed
MOT #5	2016-03-30 14:21
MOT test number	577831378278
Result	✓ Passed
MOT #4	2015-02-27 15:11
MOT test number	935828955026
Result	✓ Passed
NOT 113	2014 02 07 16 46
MOT #3 MOT test number	2014-03-07 16:46
	406796564090
Result	✓ Passed
MOT #2	2012-10-30 13:40
MOT test number	677274902389
Result	✓ Passed
MOT #1	2011-11-08 12:51
MOT test number	565752311371
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date

Category
Type

Damage 2

Date

Category
Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlowhere.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK NK
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-19
Last registration	2024-02-27
Complete history	See info



Registration #1	2008-11-19	16 mi
Registration #2	2011-11-08	11.000 mi
Registration #3	2012-10-30	13.438 mi
Registration #4	2014-03-07	16.583 mi
Registration #5	2015-02-27	18.811 mi
Registration #6	2016-03-30	21.195 mi
Registration #7	2017-03-16	22.713 mi
Registration #8	2018-03-19	24.163 mi
Registration #9	2018-10-12	24.823 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111,7177 esp

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating

Video <u>see crash video</u>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1078130

CarCheck.co.uk page 12/12