



report date: 2024-03-29

General information

Make	SMART
Model	FORTWO COUPE PASSION 71
Colour	Silver
Year of manufacture	2008
Top speed	90 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	13.3 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-17
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-12-04
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	32
Total items failed	8

MOT #20	2023-12-05 10:31
MOT test number	765684334178
Result	✓ Passed
Next expiry date	2024-12-04

MOT #19	2023-12-05 10:31
MOT test number	333901299823
Result	✗ Failed
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #18	2022-11-14 10:06
MOT test number	582289677824
Result	✓ Passed

MOT #17	2022-11-11 08:39
MOT test number	619730024271
Result	✗ Failed
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #16**

2021-11-08 11:20

MOT test number

480370781442

Result

✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2020-12-14 10:14

MOT test number

311591027966

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #14**

2019-06-26 09:12

MOT test number

386111768577

Result

✓ Passed

MOT #13

2019-06-25 16:23

MOT test number

803952165524

Result

✗ Failed

Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**MOT #12**

2018-11-07 11:36

MOT test number

912103423096

Result

✓ Passed

**MOT #11** 2017-11-07 14:20**MOT test number** 590916514505**Result** Passed**MOT #10** 2017-11-06 14:49**MOT test number** 533196378519**Result** Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #9** 2016-11-04 09:54**MOT test number** 686779169779**Result** Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2016-11-04 09:54

MOT test number

461953927590

Result**✗ Failed****Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2015-11-06 11:25

MOT test number

389174912286

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit worn on inner and outer edges (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #6**

2015-11-05 10:04

MOT test number

160818361077

Result**✗ Failed****Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Nearside Side repeater insecure (1.4.A.2b)**Advice** Nearside Front Tyre worn close to the legal limit worn on inner and outer edges (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

**MOT #5** 2014-11-06 10:39**MOT test number** 378570114398**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** NSF + NSR + OSR tyres all on 3mm**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Both front tyres cracking on outter edges**MOT #4** 2013-11-05 15:05**MOT test number** 205369403367**Result** ✓ Passed**MOT #3** 2012-10-30 11:57**MOT test number** 945264502333**Result** ✓ Passed**MOT #2** 2012-10-30 11:57**MOT test number** 199404002382**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #1** 2011-11-02 14:28**MOT test number** 419766301432**Result** ✓ Passed**Notice** Nail in nearside rear tyre



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
4 December 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	4 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	BJ58MYB
Plate since	2024-03-29
Current registration	BJ58MYB
Plate since	2024-03-29

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-11-04
Last registration	2023-12-05
Complete history	See info



Registration #1	2008-11-04	10 mi
Registration #2	2011-11-02	18.510 mi
Registration #3	2012-10-30	19.786 mi
Registration #4	2013-11-05	20.794 mi
Registration #5	2014-11-06	24.781 mi
Registration #6	2015-11-05	29.591 mi
Registration #7	2015-11-06	29.606 mi
Registration #8	2016-11-04	34.585 mi
Registration #9	2016-11-04	34.585 mi
Registration #10	2017-11-06	38.634 mi
Registration #11	2017-11-07	38.643 mi
Registration #12	2018-11-05	42.717 mi
Registration #13	2018-11-05	42.717 mi
Registration #14	2018-11-05	42.717 mi
Registration #15	2018-11-05	42.717 mi
Registration #16	2018-11-05	42.717 mi
Registration #17	2018-11-05	42.717 mi
Registration #18	2018-11-05	42.717 mi
Registration #19	2018-11-05	42.717 mi
Registration #20	2018-11-05	42.717 mi
Registration #21	2018-11-05	42.717 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	33 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21BD4139