





#### General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Blue
Year of manufacture	2003
Top speed	133 mph
0 - 60 mph	8.6 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	163 BHP
Max. torque	229 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	30.7 mpg
CO2 emission	221 g/km
CO2 label	Κ







# Internet history

Entry 2	2
Date	

Pictures

2021-07-25

11

Listing price

View report



source: autotrader.co.uk

Entry 1	
Date	2021-07-05
Pictures	11
Listing price	View report



source: autotrader.co.uk









# MOT history

MOT expiry date	2023-06-24
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	21
Total items failed	10

MOT #23	2022-06-25 12:02
MOT test number	538021261776
Result	✓ Passed
Next expiry date	2023-06-24
Advice Undertray Fitted	

MOT #22	2021-07-08 13:30
MOT test number	632333198183
Result	✓ Passed
Advice Covers fitted unable t check items	

MOT #21	2021-07-08 08:43
MOT test number	259063488498
Result	🗙 Failed
Advice Front Brake pipe corroded, covered in grease or other material t rear (1.1.11 (	c))
Advice Covers fitted unable t check items	
<b>DANGEROUS</b> Front Brake pipe leaking on a hydraulic braking system t rear (1.1.11 (b)	)) (ii))
<b>MAJOR</b> Front Brake pipe excessively corroded t rear (1.1.11 (c))	





MOT #20		2020-07-30 09:51
MOT test number		421064651300
Result		✓ Passed
MOT #19		2020-07-29 12:33
MOT test number		786260268005
Result		🗙 Failed
MAJOR Offside Front Co	il spring fractured or broken (5.3.1 (b) (i))	
MOT #18		2019-11-20 13:11
MOT test number		956936660132
Result		✓ Passed
MOT #17		2018-11-28 14:22
MOT test number		614479405693
Result		✓ Passed
MOT #16		2017-11-25 14:14
MOT test number		368996452895
Result		✓ Passed
MOT #15		2017-11-25 14:14
MOT test number		468897931962
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)	
Pass with rectification	Offside Rear Stop lamp not working (1.2.1b)	



SMO3HYN report date: 2024-03-29

MOT #14	2017-06-03 09:05
MOT test number	332123138242
Result	🗙 Failed
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice Battery loose	
Fail Offside Stop lamp not working (1.2.1b)	
<b>Fail</b> Offside Brake pipe excessively corroded front to rear at rear (3.6.B.2c)	
Advice Water in nearside headlamp	
<b>Fail</b> Nearside Front Suspension component mounting prescribed area is excessively co by battery (2.4.A.3)	orroded inner wing

MOT #13		2016-06-06 12:02
MOT test	number	885116127979
Result		✓ Passed
Advice	COVERS	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #12	2016-06-04 11:48
MOT test number	148520503437
Result	🗙 Failed
<b>Fail</b> Offside Headlamp aim beam image kick up to the offside (1.8)	
Advice COVERS	
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Fail Offside front brake binding (3.7.B.1)	



SMO3HYN report date: 2024-03-29

MOT #11		2015-05-28 15:56
MOT test	number	588258045108
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #10	2014-05-31 10:07
MOT test number	597131454197
Result	✓ Passed

MOT #9	2013-05-24 14:18
MOT test number	688264143125
Result	✓ Passed

MOT #8	2013-05-18 09:57
MOT test number	266148633481
Result	🗙 Failed
Fail Nearside Front coil spring incomplete (2.4.C.1a)	
<b>Fail</b> Offside Ball joint dust cover excessively damaged so that it no longer prevent (2.2.C.1c)	s the ingress of dirt
<b>Fail</b> Nearside Ball joint dust cover excessively damaged so that it no longer preven (2.2.C.1c)	nts the ingress of dirt

MOT #7	2012-05-25 12:43
MOT test number	518996742102
Result	✓ Passed
Notice Exhaust 2nd centre silencer corroded	



MOT #6		2011-05-18 13:33
MOT test	number	399568331122
Result		✓ Passed
Notice	Near side rear tyre 2m	
Notice	Off side rear tyre 3m	

MOT #5	2010-05-07 10:28
MOT test number	662937820113
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #4	2009-05-18 16:32
MOT test number	274608539471
Result	✓ Passed

MOT #3	2008-05-14 11:55
MOT test number	622985938167
Result	✓ Passed

MOT #2	2007-05-10 10:08
MOT test number	121240037116
Result	✓ Passed
MOT #1	2006-05-17 12:03
MOT test number	300327936139

🗸 Passed

**SM03HYN** 

report date: 2024-03-29





#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	L PWAST
Туре	K K
Damage 2	AMPLE
Damaye z	a cate of a
Date	
Category	AMPL
Туре	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
***********	
*********	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
See in this check in this MERCEDES had uncreate humber plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Carrent registration	
Carrent registration Plate since	





#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



SM03HYN report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-05-31
Last registration	2022-06-25
Complete history	See info



Registration #1	2003-05-31	16 mi
Registration #2	2006-05-17	20.954 mi
Registration #3	2007-05-10	22.300 mi
Registration #4	2008-05-14	24.649 mi
Registration #5	2009-05-18	34.309 mi
Registration #6	2010-05-07	43.262 mi
Registration #7	2011-05-18	51.587 mi
Registration #8	2012-05-25	60.131 mi
Registration #9	2013-05-18	62.435 mi
Registration #10	2013-05-24	62.450 mi
Registration #11	2014-05-31	63.534 mi
Registration #12	2015-05-28	71.971 mi
Registration #13	2016-06-04	76.388 mi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 esi
Registration #24		11.777 est
Registration #25		11.117 esi
Registration #26		11.777 est
CarChaele ea ule		

CarCheck.co.uk

More info >



## Dimensions & weight

Width	1715 mm
Height	1289 mm
Length	3995 mm
Wheel base	2400 mm
Kerb weight	1290 kg
Additional information	

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11195832481927