





report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC
Colour	Grey
Year of manufacture	2014
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	166 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



HJ64OYG

report date: 2024-03-29

Internet history

Entry 3

Date 2023-06-28

Pictures 0

Listing price View report

source: carcraft.co.uk

Entry 2

2021-06-26 Date

Pictures 37

Listing price View report









source: cargurus.co.uk


Entry 1

Date 2021-06-25

Pictures 37

Listing price View report









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-13
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #10	2023-07-14 16:41
MOT test number	888221088636
Result	✓ Passed
Next expiry date	2024-07-13
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #9	2023-07-03 10:02
MOT test number	462171874277
Result	X Failed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))	
Fail Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))	
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #8		2022-08-30 14:28
MOT test	number	935740558738
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



MOT #7 2021-07-05 12:27 **MOT test number** 630006224678 Result ✓ Passed MOT #6 2021-04-21 12:30 **MOT test number** 793395607665 Result ✓ Passed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5	2020-02-20 13:37
MOT test number	574122755765
Result	✓ Passed

	2013 03 11 17101
MOT test number	146999819909
Result	✓ Passed

MOT #3	2018-03-12 12:44
MOT test number	108321337509
Result	✓ Passed

MOT #2		2017-09-20 14:26
MOT test	number	977484113363
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front tyre outer wall scuffed/devoid of manufactures information	
Advice	Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Coolant low	

CarCheck.co.uk page 4/12



MOT #1 2017-09-20 14:26 **MOT test number** 836585920642 Result × Failed **Advice** Nearside Front tyre outer wall scuffed/devoid of manufactures information Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a) **Advice** Pass with rectification Central Rear Seat belt locking mechanism does not secure or release offside (5.2.5a)**Advice** Coolant low Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· · · · · · · · · · · · · · · · · · ·	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

2000000	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK NE.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-11-28
Last registration	2023-07-14
Complete history	See info



Registration #1	2014-11-28	22 mi
Registration #2	2017-09-20	24.233 mi
Registration #3	2017-09-20	24.233 mi
Registration #4	2018-03-12	25.955 mi
Registration #5	2019-03-11	34.519 mi
Registration #6	2020-02-20	43.109 mi
Registration #7	2021-04-21	45.098 mi
Registration #8		71.777 es
Registration #9		11.177 mi
Registration #10		11.177 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		9.700 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1486 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	54 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14NEL -19FV3062LUH

CarCheck.co.uk page 12/12