



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 AVANTGARDE
Colour	Silver
Year of manufacture	2006
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	227 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-28
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-07
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	21
Total items failed	4

MOT #18 2024-02-08 15:55

MOT test number 406903104694

Result ✓ Passed

Next expiry date 2025-02-07

Advice Front Suspension arm ball joint has slight play all (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2024-02-08 12:25

MOT test number 405188258744

Result ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm ball joint has slight play all (5.3.4 (a) (i))**Fail** Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))

MOT #16 2022-12-28 11:31

MOT test number 425156861307

Result ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2022-01-11 12:07**MOT test number** 347717512919**Result** ✓ Passed**MOT #14** 2021-01-07 11:55**MOT test number** 243529673193**Result** ✓ Passed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both sides, Rear arms bushes deteriorating (5.3.4 (a) (i))**Advice** Front Lower Suspension arm ball joint has slight play Both sides, Front arms (5.3.4 (a) (i))**MOT #13** 2019-12-04 11:02**MOT test number** 985291286332**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play Front arm (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play Front arm (5.3.4 (a) (i))**MOT #12** 2018-12-05 10:45**MOT test number** 598297166184**Result** ✓ Passed**MOT #11** 2017-11-29 11:43**MOT test number** 339586552848**Result** ✓ Passed**MOT #10** 2016-11-25 10:54**MOT test number** 418174918944**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Wipers smearing

**MOT #9** 2016-11-25 10:54**MOT test number** 456941534162**Result** ✗ Failed**Advice** Wipers smearing**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #8** 2015-11-26 11:38**MOT test number** 994300453092**Result** ✓ Passed**MOT #7** 2014-12-15 13:49**MOT test number** 559769444326**Result** ✓ Passed**MOT #6** 2014-12-15 11:15**MOT test number** 428339144444**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #5** 2014-07-03 16:58**MOT test number** 367144484128**Result** ✓ Passed**MOT #4** 2013-07-09 12:19**MOT test number** 356080093187**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #3	2012-07-16 11:44
MOT test number	148048592137
Result	✓ Passed
Advice	Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
Advice	Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)

MOT #2	2011-07-20 17:09
MOT test number	736531901223
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2009-03-02 11:19
MOT test number	624041469039
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-01
Last registration	2024-02-08
Complete history	See info



Registration #1	2006-03-01	22 mi
Registration #2	2009-03-02	17.643 mi
Registration #3	2011-07-20	19.507 mi
Registration #4	2012-07-16	24.235 mi
Registration #5	2013-07-09	27.825 mi
Registration #6	2014-07-03	31.190 mi
Registration #7	2014-12-15	36.460 mi
Registration #8	2014-12-15	36.460 mi
Registration #9	2015-11-26	51.813 mi
Registration #10	2016-11-25	68.083 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi
Registration #20	2019-05-20	75.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030275442