



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S HDI
Colour	Grey
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-22
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #22	2021-03-11 10:37
MOT test number	569857676184
Result	✓ Passed
Next expiry date	2022-03-10
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #21	2021-03-09 12:40
MOT test number	605384115115
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2020-03-05 14:14

MOT test number

556897399175

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19**

2020-03-05 11:04

MOT test number

322814801870

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Fail** Headlamp aim too low and too far to the right. (4.1.2 (a))**MOT #18**

2019-03-11 11:02

MOT test number

533037117266

Result

✓ Passed

**MOT #17** 2019-03-11 09:47**MOT test number** 815998460552**Result** ✗ Failed**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction anti pollution light (8.2.2.2 (g))**MOT #16** 2018-03-08 08:44**MOT test number** 451451869571**Result** ✓ Passed**MOT #15** 2018-03-08 08:00**MOT test number** 929785990071**Result** ✗ Failed**Fail** Nearside Front Direction indicator not working (1.4.A.2c)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Direction indicator not working (1.4.A.2c)**MOT #14** 2017-01-18 13:58**MOT test number** 574612605121**Result** ✓ Passed**MOT #13** 2017-01-18 08:31**MOT test number** 380941695193**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #12	2016-01-11 09:09
MOT test number	504664515767
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11	2014-04-24 11:56
MOT test number	685924314154
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Play in steering rack inner joint(s)
Notice	Turbo pipe insecure
Notice	Engine undertray insecure

**MOT #10** 2014-04-15 16:32**MOT test number** 255375904150**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Front Direction indicator not working (1.4.A.2c)**Notice** Play in steering rack inner joint(s)**Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Notice** Turbo pipe insecure**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Direction indicator not working (1.4.A.2c)**Notice** Engine undertray insecure**MOT #9** 2012-10-05 12:32**MOT test number** 387539572485**Result** ✓ Passed**MOT #8** 2012-10-05 12:32**MOT test number** 766909272248**Result** ✗ Failed**Pass with rectification** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

**MOT #7** 2011-10-13 15:10**MOT test number** 338696481268**Result** ✓ Passed**MOT #6** 2011-10-12 14:07**MOT test number** 315595981428**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2010-10-22 11:31**MOT test number** 280475090261**Result** ✓ Passed**MOT #4** 2010-10-15 09:59**MOT test number** 160518480207**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Rear wheel bearing rough when rotated (2.6.1)**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**MOT #3** 2009-06-09 10:20**MOT test number** 292540569112**Result** ✓ Passed**Advice** Offside Front Ball joint has slight play (2.2.B.1f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #2	2008-06-02 15:03
MOT test number	511354358113
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2008-06-02 15:03
MOT test number	793644658109
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Rear Stop lamp not working (1.2.1b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KN05UYK
Plate since	2019-03-28
Current registration	KN05UYK
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-06-08
Last registration	2021-03-11
Complete history	See info



Registration #1	2005-06-08	12 mi
Registration #2	2008-06-02	23.403 mi
Registration #3	2009-06-09	38.640 mi
Registration #4	2010-10-15	62.498 mi
Registration #5	2010-10-22	62.574 mi
Registration #6	2011-10-12	70.601 mi
Registration #7	2011-10-13	70.646 mi
Registration #8	2012-10-05	74.642 mi
Registration #9	2014-04-15	81.371 mi
Registration #10	2014-04-24	81.371 mi
Registration #11	2016-01-11	82.095 mi
Registration #12	2016-01-11	82.095 mi
Registration #13	2016-01-11	82.095 mi
Registration #14	2016-01-11	82.095 mi
Registration #15	2016-01-11	82.095 mi
Registration #16	2016-01-11	82.095 mi
Registration #17	2016-01-11	82.095 mi
Registration #18	2016-01-11	82.095 mi
Registration #19	2016-01-11	82.095 mi
Registration #20	2016-01-11	82.095 mi
Registration #21	2016-01-11	82.095 mi
Registration #22	2016-01-11	82.095 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1306 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

JB390064134