



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2017
Top speed	135 mph
0 - 100 km/h	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 2

Date	2023-02-20
Pictures	6
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2022-03-22
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)

**MOT history**

MOT expiry date	2024-12-13
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #5 2023-12-14 10:42**MOT test number** 449599297659**Result** Passed**Next expiry date** 2024-12-13**Advice** Co vers fitted**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2022-11-30 14:51**MOT test number** 628825700433**Result** Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge of tread (5.2.3 (e))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perished on outer sidewall (5.2.3 (d) (ii))**Advice** Under trays fitted covering testable items

**MOT #3** 2021-12-11 15:22**MOT test number** 373730064821**Result** ✓ Passed

- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Under 3mm (5.2.3 (e))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e))
- Advice** Offside Front Running light not working

MOT #2 2020-12-10 12:43**MOT test number** 139411571286**Result** ✓ Passed**MOT #1** 2020-06-06 05:09**MOT test number** 687735734390**Result** ✓ Passed

- Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GX17GXB
Plate since	2024-03-29
Current registration	 GX17GXB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-06-14
Last registration	2023-12-14
Complete history	See info



Registration #1	2017-06-14	23 mi
Registration #2	2020-12-10	45.771 mi
Registration #3	2021-12-11	61.831 mi
Registration #4	2022-06-20	75.277 mi
Registration #5	2022-06-20	75.277 mi
Registration #6	2022-06-20	75.277 mi
Registration #7	2023-12-14	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2712 mm
Kerb weight	1505 kg
Max. allowed weight	2100 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CRLB704765