





General information

| Make | VOLVO |
|---------------------|-------------------------------------|
| Model | XC90 D5 POWERPULSE R-DESIGN PRO AWD |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 137 mph |
| 0 - 60 mph | 7.4 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 231 BHP |
|-------------------------|---------------------|
| Max. torque | 480 Nm at 1.750 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 45.6 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |







Internet history

Entry 1

Date Pictures 2021-08-07

12

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-10-02 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 4 |
| Total items failed | 0 |

| MOT #5 | 2023-10-03 12:35 |
|----------------------------------------------------------------------------------|------------------|
| MOT test number | 131007197180 |
| Result | 🗸 Passed |
| Next expiry date 2024-10- | |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #4 | 2022-09-16 16:00 |
|-----------------|------------------|
| MOT test number | 317449949736 |
| Result | ✓ Passed |

| MOT #3 | 2021-08-24 08:40 |
|------------------------------------------------------------------------------|------------------|
| MOT test number | 846532910864 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #2 | 2020-09-11 11:25 |
|-----------------|------------------|
| MOT test number | 850922702832 |
| Result | ✓ Passed |





| MOT #1 | 2019-09-06 15:05 |
|----------------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 321357106095 |
| Result | ✓ Passed |
| AdviceUndetected peak [emissions]AdviceRear Child Seat fitted not allowing full inspection of adult belt | |



Tax & MOT check

| Tax due: 1 January 2025 | ✓ Taxed | Expires: 2 October 2024 | ✓ мот |
|-----------------------------------|------------|-----------------------------------|-----------------------|
| Tax status | | | Valid until 1 January |
| Days left | | | 248 |
| MOT expiry date | | | 2 October 2024 |
| Full MOT history | | | See MOT history |

Tax calculation

| Vehicle class | 49 |
|-----------------------------------------|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | K K K |
| Damage 2 | AMPL |
| | F Store |
| Date | 1. F |
| Category | ant |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and and a second s | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| *********** | |
| ******* | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 7 |
| First mileage registration | 2016-09-16 |
| Last registration | 2023-10-03 |
| Complete history | <u>See info</u> |



| Registration #1 | 2016-09-16 | 7 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-09-06 | 43.554 mi |
| Registration #3 | 2020-09-11 | 50.531 mi |
| Registration #4 | | 11.117 est |
| Registration #5 | | 11.117 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| \$0482 | |
| S0501 | |
| \$0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 97% |
| Children | 87% |
| Pedestrian | 72% |
| Safety systems | 94% |
| Overall rating | 89% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2008 mm |
| Height | 1776 mm |
| Length | 4950 mm |
| Wheel base | 2984 mm |
| Kerb weight | 2009 kg |
| Max. allowed weight | 2750 kg |
| Additional information | |
| Fuel tank capacity | 71 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 1801395 |