



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Black
Year of manufacture	2006
Top speed	139 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.4 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-03-26
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-08
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	40
Total items failed	6

MOT #19	2024-03-09 13:09
MOT test number	866009195112
Result	✓ Passed
Next expiry date	2025-03-08
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2023-03-02 09:58
MOT test number	749224007843
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-02-11 10:55
MOT test number	429430576941
Result	✓ Passed

**MOT #16**

2022-02-10 14:23

MOT test number

468578169718

Result

✗ Failed

Fail Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Fail** Offside Front Position lamp not working head (4.2.1 (a) (ii))**MOT #15**

2021-02-09 11:46

MOT test number

382656053112

Result

✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both torque reaction arms (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14**

2021-02-09 11:15

MOT test number

984982680204

Result

✗ Failed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both torque reaction arms (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

**MOT #13**

2020-02-21 12:01

MOT test number

695311669390

Result

✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both Torque reaction arms (5.3.4 (a) (i))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Play in steering rack inner joint(s) Tie Rod

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #12

2020-02-21 09:43

MOT test number

951407144069

Result

✗ Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both Torque reaction arms (5.3.4 (a) (i))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Play in steering rack inner joint(s) Tie Rod

**MOT #11** 2019-02-16 10:58**MOT test number** 657587282198**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both side (deteriorated) (5.3.4 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside rear tyre slightly deteriorated**MOT #10** 2018-03-03 12:02**MOT test number** 152879555465**Result** ✓ Passed**Advice** Front Torque/reaction arm has a slightly deteriorated rubber bush both (2.4.G.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #9** 2017-02-07 09:09**MOT test number** 216857841800**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #8** 2016-03-08 09:09**MOT test number** 103891220419**Result** ✓ Passed**Advice** Offside Rear nail in tyre**MOT #7** 2015-02-23 09:10**MOT test number** 485194455090**Result** ✓ Passed

**MOT #6** 2014-03-03 07:50**MOT test number** 157802164420**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2013-02-18 08:01**MOT test number** 127019543484**Result** ✓ Passed**MOT #4** 2012-03-08 07:47**MOT test number** 847038662033**Result** ✓ Passed**MOT #3** 2011-03-11 12:13**MOT test number** 949680471071**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-02-26 10:29**MOT test number** 682737050079**Result** ✓ Passed**MOT #1** 2009-03-09 16:56**MOT test number** 830758869068**Result** ✓ Passed**Notice** Earth wiring behind nearside inner wing shield could do with better securing**Notice** Nail in offside rear tyre



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
8 March 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 FE06AEA
Plate since	2024-03-28
Current registration	 FE06AEA
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-13
Last registration	2024-03-09
Complete history	See info



Registration #1	2006-03-13	17 mi
Registration #2	2009-03-09	18.929 mi
Registration #3	2010-02-26	23.659 mi
Registration #4	2011-03-11	29.075 mi
Registration #5	2012-03-08	32.945 mi
Registration #6	2013-02-18	34.921 mi
Registration #7	2014-03-03	35.904 mi
Registration #8	2015-02-23	36.860 mi
Registration #9	2016-03-08	38.951 mi
Registration #10	2017-02-07	41.485 mi
Registration #11	2018-03-03	44.747 mi
Registration #12	2019-03-09	48.009 mi
Registration #13	2020-03-09	51.271 mi
Registration #14	2021-03-09	54.533 mi
Registration #15	2022-03-09	57.795 mi
Registration #16	2023-03-09	61.057 mi
Registration #17	2024-03-09	64.319 mi
Registration #18	2025-03-09	67.581 mi
Registration #19	2026-03-09	70.843 mi
Registration #20	2027-03-09	74.105 mi
Registration #21	2028-03-09	77.367 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1665 kg
Max. allowed weight	2135 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030735534