



PEUGEOT

VK07HA0

report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 SPORT HDI
Colour	Silver
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg






## Internet history

### Entry 2

Date	2023-01-08
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

### Entry 1

Date	2021-02-03
Pictures	0
Listing price	<a href="#">View report</a>

source: autoonline.co.uk



## MOT history

MOT #24	2024-02-22 13:52
MOT test number	557759691923
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #23	2023-02-21 14:35
MOT test number	548740028907
Result	✓ Passed

MOT #22	2022-02-23 14:35
MOT test number	587273854634
Result	✓ Passed

MOT #21	2022-02-23 14:35
MOT test number	577625239277
Result	✗ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #20	2021-02-18 15:37
MOT test number	177569686948
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19**

2021-02-16 12:16

**MOT test number**

692499310029

**Result****✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both and n/s red in colour (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt adrift (2.1.3 (g) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Fuel additive tank strap corroded away

**MOT #18**

2020-02-24 10:07

**MOT test number**

889681950626

**Result****✓ Passed**

- Advice** Play in steering rack inner joint(s)

**MOT #17** 2020-02-21 16:40**MOT test number** 594515122325**Result** ✗ Failed**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Play in steering rack inner joint(s)**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn Drop Link (5.3.4 (a) (i))**MOT #16** 2019-02-20 15:16**MOT test number** 940899647659**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15** 2019-02-20 11:06**MOT test number** 375702405995**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2018-02-22 15:05**MOT test number** 203980189150**Result** ✓ Passed**MOT #13** 2017-02-27 10:47**MOT test number** 564875179628**Result** ✓ Passed

**MOT #12** 2016-02-24 11:52**MOT test number** 694132079526**Result** ✓ Passed**MOT #11** 2016-02-23 11:09**MOT test number** 956015684310**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #10** 2015-03-04 14:40**MOT test number** 525793565058**Result** ✓ Passed**MOT #9** 2014-03-05 09:06**MOT test number** 727234664032**Result** ✓ Passed**MOT #8** 2014-03-04 11:45**MOT test number** 515003364083**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2013-02-14 11:24**MOT test number** 416505643033**Result** ✓ Passed**Notice** Nearside and offside rear brake discs in poor condition**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-02-14 11:24**MOT test number** 128585143447**Result** ✗ Failed**Notice** Nearside and offside rear brake discs in poor condition**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2012-02-08 16:01**MOT test number** 959379032067**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-02-08 12:00**MOT test number** 185619332057**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Inner Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2011-03-03 15:25**MOT test number** 159612861061**Result** ✓ Passed**MOT #2** 2011-03-03 11:29**MOT test number** 509492161036**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Mechanical brake component has restricted free movement (3.5.1k)



MOT #1	2010-03-04 13:00
MOT test number	142803360423
Result	✓ Passed





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-03-06
Last registration	2024-02-22
Complete history	<a href="#">See info</a>



Registration #1	2007-03-06	29 mi
Registration #2	2010-03-04	40.096 mi
Registration #3	2011-03-03	53.956 mi
Registration #4	2011-03-03	53.956 mi
Registration #5	2012-02-08	61.916 mi
Registration #6	2012-02-08	61.917 mi
Registration #7	2013-02-14	66.796 mi
Registration #8	2014-03-04	71.944 mi
Registration #9	2014-03-05	71.944 mi
Registration #10	2015-03-04	76.943 mi
Registration #11	2016-02-23	83.025 mi
Registration #12	2016-02-24	83.047 mi
Registration #13	2017-02-27	87.647 mi
Registration #14	2018-03-01	91.317 mi
Registration #15	2018-03-01	91.317 mi
Registration #16	2018-03-01	91.317 mi
Registration #17	2018-03-01	91.317 mi
Registration #18	2018-03-01	91.317 mi
Registration #19	2018-03-01	91.317 mi
Registration #20	2018-03-01	91.317 mi
Registration #21	2018-03-01	91.317 mi
Registration #22	2018-03-01	91.317 mi
Registration #23	2018-03-01	91.317 mi
Registration #24	2018-03-01	91.317 mi
Registration #25	2018-03-01	91.317 mi
Registration #26	2018-03-01	91.317 mi

**More info** >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1530 mm
Length	4211 mm
Wheel base	2608 mm
Kerb weight	1335 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JB893025088