



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F









Internet history

Entry 1

Date	2022-01-16
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-22
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	24
Total items failed	10

MOT #21	2024-03-12 20:09
MOT test number	934624290090
Result	✓ Passed
Next expiry date	2025-03-22
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #20	2024-03-12 20:09
MOT test number	717056826947
Result	✗ Failed
Pass with rectification	Windscreen washer not working (3.5 (a))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #19**

2023-03-20 10:55

**MOT test number**

771667434993

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #18**

2023-03-20 10:55

**MOT test number**

377998258833

**Result**

✗ Failed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Brake hydraulic reservoir fluid level significantly below minimum level (1.1.10 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2022-03-01 14:49

**MOT test number**

345768912555

**Result**

✓ Passed

**Advice**

Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16**

2021-03-09 16:14

**MOT test number**

560006010527

**Result**

✓ Passed

**MOT #15**

2021-03-09 14:26

**MOT test number**

789022405405

**Result**

✗ Failed

**Fail**

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #14**

2020-03-23 17:25

**MOT test number**

817553293379

**Result**

✓ Passed

**MOT #13** 2020-03-19 11:11**MOT test number** 642530936921**Result** ✗ Failed**Fail** Central Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Lower Steering linkage ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**MOT #12** 2019-03-18 16:01**MOT test number** 173415608551**Result** ✓ Passed**MOT #11** 2019-03-07 14:38**MOT test number** 384595261948**Result** ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Pass with rectification** Windscreen washer not working (3.5 (a))**MOT #10** 2018-03-16 16:03**MOT test number** 884058262050**Result** ✓ Passed**Advice** Nearside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #9** 2018-03-12 15:22**MOT test number** 240089070923**Result** ✗ Failed**Fail** Offside Rear Lower coil spring broken (2.4.C.1a)**Fail** Offside Front Upper coil spring fractured (2.4.C.1a)



<b>MOT #8</b>	2017-02-20 16:32
---------------	------------------

<b>MOT test number</b>	751438645744
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2016-03-18 09:58
---------------	------------------

<b>MOT test number</b>	700039670389
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2015-03-23 09:37
---------------	------------------

<b>MOT test number</b>	149842685407
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2014-03-24 09:32
---------------	------------------

<b>MOT test number</b>	989053584094
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2013-03-18 09:12
---------------	------------------

<b>MOT test number</b>	987117373051
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
---------------	--

<b>Advice</b>	Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
---------------	---

<b>MOT #3</b>	2012-03-20 11:57
---------------	------------------

<b>MOT test number</b>	286310582070
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-03-31 11:51
---------------	------------------

<b>MOT test number</b>	648250791024
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #1	2010-03-30 13:45
MOT test number	640149880073
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
22 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	22 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>YK07OHZ</b>
Plate since	2019-06-29
Current registration	 <b>YK07OHZ</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-01
Last registration	2024-03-12
Complete history	<a href="#">See info</a>



Registration #1	2007-03-01	15 mi
Registration #2	2010-03-30	8.442 mi
Registration #3	2011-03-31	13.205 mi
Registration #4	2012-03-20	16.264 mi
Registration #5	2013-03-18	21.913 mi
Registration #6	2014-03-24	28.061 mi
Registration #7	2015-03-23	32.734 mi
Registration #8	2016-03-18	38.916 mi
Registration #9	2017-02-20	42.749 mi
Registration #10	2018-03-12	50.532 mi
Registration #11	2019-03-20	55.337 mi
Registration #12	2020-03-20	59.337 mi
Registration #13	2021-03-20	63.337 mi
Registration #14	2022-03-20	67.337 mi
Registration #15	2023-03-20	71.337 mi
Registration #16	2024-03-20	75.337 mi
Registration #17	2025-03-20	79.337 mi
Registration #18	2026-03-20	83.337 mi
Registration #19	2027-03-20	87.337 mi
Registration #20	2028-03-20	91.337 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622