





General information

| Make | FIAT |
|---------------------|------------------------|
| Model | 500L MULTIJET POP STAR |
| Colour | Green |
| Year of manufacture | 2014 |
| Top speed | 102 mph |
| 0 - 60 mph | 15.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 85 BHP | | |
|-------------------------|---------------------|--|--|
| Max. torque | 200 Nm at 1.500 rpm | | |
| Engine capacity | 1.248 cc | | |
| Cylinders | 4 | | |
| Fuel type | Diesel | | |
| Consumption city | 56.5 mpg | | |
| Consumption extra urban | 76.3 mpg | | |
| Consumption combined | 67.3 mpg | | |
| CO2 emission | 110 g/km | | |
| CO2 label | В | | |







Internet history

Date Pictures 2022-06-05

3

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-06-15 |
|--------------------|------------|
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 12 |
| Total items failed | 3 |

| MOT #10 | 2023-06-08 15:02 |
|--|---|
| MOT test number | 746635318863 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-15 |
| Advice Engine covers, under trays & s | ill covers are fitted thus not allowing full inspection |
| Advice Nearside Rear Nail in tyre also | getting close to the legal limit |
| Advice Exhaust emissions are too clea | n to get a reading |
| Advice Nearside Front Shock absorber | s has light misting of oil (5.3.2 (b)) |

| МОТ #9 | 2022-06-16 11:32 |
|-----------------|------------------|
| MOT test number | 286620290816 |
| Result | ✓ Passed |
| | |

| MOT #8 | 2022-06-15 09:09 |
|---|------------------|
| MOT test number | 316948902390 |
| Result | 🗙 Failed |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |





| MOT #7 | 2021-08-26 11:31 | | |
|---|---------------------------------|--|--|
| MOT test number 447 | | | |
| Result | ✓ Passed | | |
| Minor Nearside Windscreen damaged but not adversely affecti | ing driver's view (3.2 (a) (i)) | | |
| MOT #6 | 2021-08-26 11:25 | | |
| MOT test number 58211301070 | | | |
| Result | 🗙 Failed | | |
| Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | | | |

FailNearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

| MOT #5 | | 2020-08-18 12:15 |
|----------|--|------------------|
| MOT test | number | 458565448988 |
| Result | | ✓ Passed |
| Advice | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Rear Nail in tyre | |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Rear Nail in tyre | |

| МОТ #4 | 2019-04-16 12:48 |
|-----------------|------------------|
| MOT test number | 525914825573 |
| Result | ✓ Passed |

| MOT #3 | 2019-04-16 12:48 |
|--------------------------------------|--|
| MOT test number | 395065310240 |
| Result | × Failed |
| Pass with rectification (ii)) | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) |



| W | D1 | 4 | F | 0 | Ν |
|----|-----------|------|----|------|------|
| re | port d | late | 20 | 24-0 | 3-29 |

| MOT #2 | 2018-04-19 12:14 |
|---------------------------|------------------|
| MOT test number | 602651181354 |
| Result | Passed |
| Advice Undertrays fitted | |
| | |
| MOT #1 | 2017-07-07 10:29 |
| MOT test number | 697306458943 |
| Result | ✓ Passed |
| Advice Nail in o/s/r tyre | |



wol4FON report date: 2024-03-29

Tax & MOT check

| ✓ Taxed Tax due: 1 June 2024 | ✓ MOT Expires: 15 June 2024 |
|---------------------------------------|--------------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 15 June 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second | |
|---|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2014-07-11 |
| Last registration | 2023-06-08 |
| Complete history | See info |



| Registration #1 | 2014-07-11 | 18 mi |
|------------------------------------|------------|--|
| Registration #2 | 2017-07-07 | 21.588 mi |
| Registration #3 | 2018-04-19 | 23.589 mi |
| Registration #4 | 2019-04-16 | 32.953 mi |
| Registration #5 | 2019-04-16 | 32.953 mi |
| Registration #6 | 2020-08-18 | 39.211 mi |
| | | |
| Registration #7 | | 11.777 mi |
| Registration #7 Registration #8 | | 10.000 est |
| | | 01,000 est 01,000 est 01,000 est |
| Registration #8 | | 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #8 Registration #9 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |

More info \rightarrow





Car features

| S0225 | Air conditionin |
|--------|-----------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 78% |
| Pedestrian | 65% |
| Safety systems | 71% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|---------------------------------|--------------------|
| Width | 1784 mm |
| Height | 1667 mm |
| Length | 4352 mm |
| Kerb weight | 1315 kg |
| Max. allowed weight | 2020 kg |
| Additional information | |
| Fuel tank capacity | 50 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Engine number CarCheck.co.uk | 5377220 page 12/12 |