



General information

Make	FORD
Model	S-MAX ZETEC
Colour	Silver
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-16
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-27
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	38
Total items failed	8

MOT #20	2023-11-28 17:32
MOT test number	517560922278
Result	✓ Passed
Next expiry date	2024-11-27

MOT #19	2023-08-17 11:22
MOT test number	414525264616
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #18** 2022-08-31 15:32**MOT test number** 388652720360**Result** ✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17 2022-08-31 10:40**MOT test number** 282812875052**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #16 2021-06-09 16:07**MOT test number** 736770491130**Result** ✓ Passed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #15 2020-10-22 15:57**MOT test number** 172441672026**Result** ✓ Passed



MOT #14	2019-10-15 12:25
---------	------------------

MOT test number	549311133619
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #13	2018-10-15 10:50
---------	------------------

MOT test number	472799833189
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #12	2018-10-15 10:50
---------	------------------

MOT test number	281915484194
-----------------	--------------

Result	✗ Failed
--------	----------

Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
-------------------------	---

MOT #11	2017-10-16 08:44
---------	------------------

MOT test number	566995120250
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Nearside Rear Nail in tyre
--------	----------------------------

Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
--------	--

Advice	Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)
--------	--

Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
--------	---

Advice	Offside Rear Tyre worn close to the legal limit 2.mm (4.1.E.1)
--------	--

**MOT #10** 2017-10-16 08:44**MOT test number** 946248470244**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit 2.mm (4.1.E.1)**Advice** Nearside Rear Nail in tyre**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)**MOT #9** 2016-09-26 12:49**MOT test number** 211022316343**Result** ✓ Passed**Advice** Both rear tyres showing signs of perishing.**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-09-26 12:02**MOT test number** 170578202086**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Both rear tyres showing signs of perishing.**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2015-09-30 13:47**MOT test number** 410467243955**Result** ✓ Passed**MOT #6** 2014-10-15 15:11**MOT test number** 397138184428**Result** ✓ Passed**MOT #5** 2014-10-15 10:05**MOT test number** 348388484204**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #4** 2013-10-17 16:49**MOT test number** 607570093270**Result** ✓ Passed**MOT #3** 2013-10-15 11:02**MOT test number** 357968583473**Result** ✗ Failed**Fail** Offside Front Side repeater not working (1.4.A.2c)**MOT #2** 2012-10-20 11:34**MOT test number** 238134392263**Result** ✓ Passed



MOT #1	2012-10-20 11:34
MOT test number	517374992265
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 November 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	27 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-28
Current registration	*****
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-22
Last registration	2023-11-28
Complete history	See info



Registration #1	2009-10-22	20 mi
Registration #2	2012-10-20	14.732 mi
Registration #3	2013-10-15	19.825 mi
Registration #4	2013-10-17	19.865 mi
Registration #5	2014-10-15	25.180 mi
Registration #6	2014-10-15	25.180 mi
Registration #7	2015-09-30	30.387 mi
Registration #8	2016-09-26	35.627 mi
Registration #9	2016-09-26	35.627 mi
Registration #10	2017-10-16	40.211 mi
Registration #11	2017-10-16	40.211 mi
Registration #12	2018-10-16	45.395 mi
Registration #13	2018-10-16	45.395 mi
Registration #14	2019-10-16	50.579 mi
Registration #15	2019-10-16	50.579 mi
Registration #16	2020-10-16	55.763 mi
Registration #17	2020-10-16	55.763 mi
Registration #18	2021-10-16	60.947 mi
Registration #19	2021-10-16	60.947 mi
Registration #20	2022-10-16	66.131 mi
Registration #21	2023-11-28	71.315 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9K82887