



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Green
Year of manufacture	2012
Top speed	124 mph
0 - 100 km/h	11.1 seconds
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





## Internet history

### Entry 2


Date	2021-06-18
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

### Entry 1

Date	2021-05-24
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-01
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	30
Total items failed	5

## MOT #14 2024-02-02 09:57

MOT test number 608282803728

Result ✓ Passed

Next expiry date 2025-02-01

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Stop lamp(s) non-obligatory stop lamp not working high level brake light (4.3.1 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

## MOT #13 2022-07-20 09:43

MOT test number 419409585982

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #12** 2021-07-09 12:48**MOT test number** 249833457489**Result** ✓ Passed**MOT #11** 2021-07-05 12:29**MOT test number** 774805704507**Result** ✗ Failed**Fail** Nearside Rear Suspension arm pin or bush excessively worn Trailing arm front bush (5.3.4 (a) (i))**Advice** Offside Front Nail in tyre**Fail** Offside Rear Suspension arm pin or bush excessively worn Trailing arm front bush (5.3.4 (a) (i))**MOT #10** 2021-01-05 09:24**MOT test number** 902058864835**Result** ✓ Passed**MOT #9** 2020-01-03 15:15**MOT test number** 504631949575**Result** ✓ Passed**MOT #8** 2020-01-03 09:24**MOT test number** 579727691807**Result** ✗ Failed**Fail** Drive shaft joint constant velocity boot missing BOTH N /SIDE AND O/SIDE (6.1.7 (g) (ii))**MOT #7** 2019-01-07 10:20**MOT test number** 887978153749**Result** ✓ Passed

**MOT #6** 2018-01-03 12:34**MOT test number** 909679971702**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Rear Direction indicator slightly discoloured nearside & offside (1.4.A.2f)**MOT #5** 2017-01-10 11:31**MOT test number** 507393723937**Result** ✓ Passed**Advice** Engine undertray fitted**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Engine cover fitted**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2017-01-10 11:31**MOT test number** 835382118902**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Engine cover fitted**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Engine undertray fitted

**MOT #3** 2016-08-24 10:16**MOT test number** 148671842814**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Engine cover fitted**Advice** Nearside Front brake disc has slight wear**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Engine undertray fitted**Advice** Offside Front brake disc has slight wear**MOT #2** 2015-11-04 12:56**MOT test number** 592836273191**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2015-01-15 14:41**MOT test number** 135185415016**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
1 February 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	1 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>CV12OXU</b>
Plate since	2019-03-28
Current registration	<b>CV12OXU</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-03-19
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2012-03-19	21 mi
Registration #2	2015-01-15	17.411 mi
Registration #3	2015-11-04	20.486 mi
Registration #4	2016-08-24	24.423 mi
Registration #5	2017-01-10	26.224 mi
Registration #6	2017-01-10	26.224 mi
Registration #7	2018-01-03	31.625 mi
Registration #8	2019-01-07	39.026 mi
Registration #9	2020-01-03	46.346 mi
Registration #10	2020-01-03	46.346 mi
Registration #11	2020-01-03	46.346 mi
Registration #12	2020-01-03	46.346 mi
Registration #13	2020-01-03	46.346 mi
Registration #14	2020-01-03	46.346 mi
Registration #15	2020-01-03	46.346 mi
Registration #16	2020-01-03	46.346 mi
Registration #17	2020-01-03	46.346 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1631 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number	BS48457
---------------	---------