





General information

Make	MERCEDES
Model	CLK CLK280 SPORT
Colour	Black
Year of manufacture	2008
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	229 g/km
CO2 label	L







Internet history

Entry 1

Date Pictures 2021-07-16

10

Listing price

View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-07-30
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	37
Total items failed	12

MOT #21		2023-07-31 10:50
MOT test	number	418103469794
Result		✓ Passed
Next exp	iry date	2024-07-30
Advice	Offside Headlamp has a product on the lens but not seriously reducing light	t output (4.1.4 (b))
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Headlamp has a product on the lens but not seriously reducing lig	ht output (4.1.4 (b))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))





OT #20 2023-07-27 12:29
OT test number 873602404042
esult × Failed
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 b) (i))
Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice Parking brake has little reserve travel
Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Advice Exhaust mounting defective (6.1.2 (a))
Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt rear 5.3.4 (b) (ii))
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Fail Windscreen washer not working (3.5 (a))
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #19	2022-06-23 13:06
MOT test number	319602658750
Result	✓ Passed



FV57	OTL
report date:	2024-03-29

MOT #18	2022-06-22 14:27
MOT test number	359836820332
Result	🗙 Failed
Fail Front Service brake excessively fluctuating (1.2.1 (e)) Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6)	(c))

MOT #17	2021-07-23 11:59
MOT test number	892136690275
Result	✓ Passed

МОТ #16	2021-07-19 11:11	
MOT test number	753733925611	
Result	🗙 Failed	
Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))		
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #15		2021-03-03 10:48
MOT test	number	226990170972
Result		✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front tyre tread getting low	

MOT #14	2020-03-02 10:54
MOT test number	629181395420
Result	✓ Passed



MOT #13	;	2019-03-05 11:49
MOT test	t number	700348041858
Result		✓ Passed
Advice	Front brake discs slightly worn	
Advice	Rear brake pads low	
Advice	Rear brake discs corroded	
MOT #12	2	2018-03-14 10:24

 MOT test number
 857751538038

 Result
 ✓ Passed

 Advice
 Offside Front tyre sidewall slightly damaged

 Advice
 Nearside Rear tyre sidewall slightly damaged

MOT #11	2018-03-08 16:28
MOT test number	518775164059
Result	🗙 Failed
Advice Offside Front tyre sidewall slightly damaged Fail Nearside Front Suspension arm has excessive play in a ball joint rear arm (2.4.G.2) Advice Nearside Deep type sidewall slightly damaged	
Advice Nearside Rear tyre sidewall slightly damaged	

MOT #10	2017-03-14 09:47
MOT test number	803519094564
Result	✓ Passed
MOT #9	2016-04-19 09:51
MOT test number 719608329412	
Result	✓ Passed
Advice The handbrake performance only just met requirements and ma	ay need adjustment







MOT #8	2015-04-23 15:40
MOT test number	386623815190
Result	✓ Passed
MOT #7	2014-07-02 10:08
MOT test number	745443384163
Result	✓ Passed
Notice Noise from rear brakes	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #6	2013-05-31 09:56
MOT test number	876831553141
Result	✓ Passed

MOT #5	2013-05-30 12:21
MOT test number	875500453113
Result	🗙 Failed
Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)	

MOT #4	2012-06-06 10:04
MOT test number	527778752112
Result	✓ Passed
MOT #3	2011-10-10 16:13
MOT test number	347783481290

Result

🗸 Passed



MOT #2	2011-10-06 11:21
MOT test number	619029171231
Result	🗙 Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #1		2011-01-18 13:01
MOT test	number	518168911022
Result		Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Nearside Front wheel bearing has slight play (2.5.A.3c)	

FV57OTL report date: 2024-03-29



Tax & MOT check

✓ Taxed Tax due: 1 April 2025	✓ MOT Expires: 30 July 2024
Tax status	Valid until 1 April
Days left	336
MOT expiry date	30 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	 AMPLI
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-01-07
Last registration	2023-07-31
Complete history	See info



Registration #1	2008-01-07	17 mi
Registration #2	2011-01-18	36.540 mi
Registration #3	2011-10-06	48.984 mi
Registration #4	2011-10-10	49.052 mi
Registration #5	2012-06-06	53.752 mi
Registration #6	2013-05-30	60.747 mi
Registration #7	2013-05-31	60.753 mi
Registration #8	2014-07-02	66.079 mi
Registration #9	2015-04-23	69.063 mi
Registration #10	2016-04-19	75.411 mi
Registration #11	2017-03-14	81.512 mi
Registration #12	2018-03-08	90.407 mi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.117 esi
Registration #16		11.777 esi
Registration #17		11.117 est
Registration #18		11.777 esi
Registration #19		11.777 esi
Registration #20		11.117 est
Registration #21		11.117 esi
Registration #22		11.117 est
Registration #23		
Registration #25		

More info >





Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg

Additional information

Fuel tank capacity	62
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030954540