



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	B-CLASS B200 CDI SE
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	300 Nm at 3.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg



LABEL UNKNOWN



MOT history

MOT #18 2022-10-05 15:25

MOT test number 791741563928

Result ✓ Passed

Next expiry date 2023-10-04

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Play in steering rack inner joint(s)

MOT #17 2021-08-26 16:12

MOT test number 781153229523

Result ✓ Passed

**MOT #16**

2020-08-27 15:28

**MOT test number**

555085833585

**Result**

✓ Passed

- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Under trays fitted obscuring view of some testable items

**MOT #15**

2020-08-27 10:25

**MOT test number**

971861558507

**Result****✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Fail** Nearside Rear Brake performance not tested suspension spring broken (1.2.1 (g))**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Under trays fitted obscuring view of some testable items**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

**MOT #14**

2019-08-15 09:26

**MOT test number**

129583067456

**Result**

✓ Passed

- Advice** Rear wiper blade damaged
- Advice** Plastic sill covers fitted obscuring the view of some components
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer tread (5.2.3 (e))
- Advice** Under trays fitted obscuring the view of some components
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))

**MOT #13**

2019-08-14 09:28

**MOT test number**

247867613174

**Result**

✗ Failed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Rear wiper blade damaged
- Advice** Plastic sill covers fitted obscuring the view of some components
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))
- Fail** Offside Front Service brake excessively fluctuating + imbalance, front axle (1.2.1 (e))
- Advice** Under trays fitted obscuring the view of some components
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer tread (5.2.3 (e))



MOT #12	2018-09-04 15:10
MOT test number	126678972877
Result	✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #11	2018-08-28 11:33
MOT test number	128419463907
Result	✗ Failed
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Minor	Offside Front Brake hose slightly chafed (1.1.12 (b) (i))
Fail	Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail	Windscreen washer not working (3.5 (a))
Fail	Fluid leaking continuously posing a serious risk to road safety fuel tank filler and over flow necks heavily corroded (8.4.1 (a) (ii))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #10	2017-09-04 15:14
MOT test number	292440324095
Result	✓ Passed



MOT #9	2017-09-01 16:18
MOT test number	308580595083
Result	✗ Failed
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Nearside Brake pipe excessively corroded Front to rear (3.6.B.2c)
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Exhaust system not adequately supported Fouling on anti-roll bar (7.1.1)
Fail	Offside Brake pipe excessively corroded Front to rear (3.6.B.2c)
Fail	Brake performance not tested Brake pipe burst during test (3.7.A.1)
Advice	Oil leak

**MOT #8**

2017-08-15 13:00

**MOT test number**

375993562562

**Result****✗ Failed****Advice** Coil springs corroded**Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)**Advice** Covers fitted**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake discs corroded, worn and scored**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Nearside & offside front tyre scrubbed off bald close to limit**Fail** Offside Front Wheel bolt(s) missing (4.2.A.1e)**Fail** Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Front brake discs corroded and worn**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #7**

2016-02-11 14:28

**MOT test number**

188504480923

**Result****✓ Passed**



**MOT #6** 2016-02-11 11:14**MOT test number** 936208707482**Result** ✗ Failed

- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #5** 2014-12-17 10:33**MOT test number** 437551054444**Result** ✓ Passed**MOT #4** 2013-10-22 11:34**MOT test number** 417645193266**Result** ✓ Passed**MOT #3** 2012-11-12 09:56**MOT test number** 758967312336**Result** ✓ Passed**MOT #2** 2011-11-16 10:54**MOT test number** 926770421369**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-11-12 11:57
MOT test number	782306110345
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>KN57VEX</b>
Plate since	2019-03-29
Current registration	 <b>KN57VEX</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-16
Last registration	2022-10-05
Complete history	<a href="#">See info</a>



Registration #1	2007-11-16	26 mi
Registration #2	2010-11-12	31.217 mi
Registration #3	2011-11-16	44.791 mi
Registration #4	2012-11-12	57.139 mi
Registration #5	2013-10-22	70.198 mi
Registration #6	2014-12-17	82.457 mi
Registration #7	2016-02-11	101.931 mi
Registration #8	2016-02-11	101.933 mi
Registration #9	2017-08-15	124.431 mi
Registration #10	2017-09-01	124.492 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2019-05-20	151.377 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi
Registration #18	2019-05-20	151.377 mi
Registration #19	2019-05-20	151.377 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5



**Number of axles**

2

**Engine number**

64094130323012