





report date: 2024-03-28

General information

Make	BMW
Model	530 530D AC
Colour	Blue
Year of manufacture	2007
Top speed	154 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	232 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg
CO2 emission	176 g/km
CO2 label	1



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-01


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-07-28
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-08-09
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	29
Total items failed	0

MOT #18		2023-08-09 08:32
MOT test	number	271063891335
Result		✓ Passed
Next expi	ry date	2024-08-09
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Nearside Rear Outer Drive shaft joint constant velocity boot severely dete	riorated (6.1.7 (g) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #17 2023-08-08 15:37 **MOT** test number 135361565508 Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAIOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Minor Nearside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

MOT test number

Result

Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))

MOT test number

Result

Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))

MAJOR

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

 MOT #14
 2021-08-10 15:15

 MOT test number
 441555266804

 Result
 ✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Rear Upper Suspension arm ball joint excessively worn Rear (5.3.4 (a) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #10
 2018-09-14 13:07

 MOT test number
 551088697760

 Result
 ✓ Passed

 MOT #9
 2017-09-12 14:39

 MOT test number
 463271253179

 Result
 ✓ Passed

 Advice
 Emissions too clean to test

CarCheck.co.uk page 5/14



MOT #3

Result

MOT test number

PF57CVP

report date: 2024-03-28

2011-09-23 12:48 237646761228

✓ Passed

MOT #8	2016-10-05 08:48
MOT test number	366961566262
Result	✓ Passed
MOT #7	2015-09-29 11:39
MOT test number	245840136694
Result	✓ Passed
Advice Under bonnet covers fitted obscuring some items	
Advice Under trays fitted obscuring some items	
MOT #6	2014-10-08 09:04
MOT test number	315681284419
Result	✓ Passed
MOT #5	2013-09-20 09:16
MOT test number	247733263258
Result	✓ Passed
	2012 10 10 10 17
MOT #4	2012-10-10 10:47
MOT test number	845314282289
Result	✓ Passed

MOT #2	2010-10-20 11:49
MOT test number	391273190496
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2010-09-02 09:31

MOT test number 230355840222

Result ✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>b</u>	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK ZIC
Plate since	
Current registration	UK ZIS
Plate sizes	

CarCheck.co.uk page 11/14



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-11-09
Last registration	2023-08-09
Complete history	See info



Registration #1	2007-11-09	18 mi
Registration #2	2010-09-02	40.446 mi
Registration #3	2010-10-20	40.673 mi
Registration #4	2011-09-23	49.060 mi
Registration #5	2012-10-10	59.209 mi
Registration #6	2013-09-20	67.166 mi
Registration #7	2014-10-08	74.699 mi
Registration #8	2015-09-29	83.404 mi
Registration #9	2016-10-05	93.105 mi
Registration #10	2017-09-12	100.822 mi
Registration #11	2018-09-14	116.234 mi
Registration #12		71.777 es
Registration #13		71.777 66
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		71.777 66
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		71.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm

Additional information

Number of seats	5
Number of axles	2
Engine number	24656682

CarCheck.co.uk page 14/14