



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Silver
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	171 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-02-04
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-07
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	27
Total items failed	3

MOT #19	2024-01-08 16:49
MOT test number	805448039836
Result	✓ Passed
Next expiry date	2025-01-07
Advice	Oil leak, but not excessive transmissions (8.4.1 (a) (i))
Advice	Front Power steering component has slight seepage from a component (2.1.5 (a))

MOT #18	2024-01-08 14:33
MOT test number	451792439578
Result	✗ Failed
Advice	Front Power steering component has slight seepage from a component (2.1.5 (a))
Advice	Oil leak, but not excessive transmissions (8.4.1 (a) (i))
MAJOR	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #17** 2022-10-29 08:33**MOT test number** 723331363681**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2021-10-26 18:42**MOT test number** 652208691872**Result** ✓ Passed**MOT #15** 2021-10-25 18:33**MOT test number** 907415835767**Result** ✗ Failed

- MAJOR** Nearside Front Tyre(s) of different size tyres are fitted on twin wheels (5.2.3 (b))
- MAJOR** Front Headlamp aim too low (4.1.2 (a))

MOT #14 2020-10-31 16:51**MOT test number** 639768749452**Result** ✓ Passed

- Advice** Exhaust hangers corroded
- Advice** Under trays cover obscuring some underside components

**MOT #13** 2019-01-31 17:21**MOT test number** 350572702614**Result** ✓ Passed**Advice** Exhaust hangers corroded**MOT #12** 2018-12-13 13:51**MOT test number** 165197223422**Result** ✗ Failed**Advice** Exhaust hangers corroded**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #11** 2016-04-06 13:43**MOT test number** 782293731170**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #10** 2015-03-19 17:52**MOT test number** 738088675035**Result** ✓ Passed**MOT #9** 2015-03-18 15:58**MOT test number** 656027775056**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #8** 2014-03-17 14:40**MOT test number** 499606974097**Result** ✓ Passed**MOT #7** 2013-03-28 10:20**MOT test number** 186557883450**Result** ✓ Passed**MOT #6** 2012-04-14 11:35**MOT test number** 487805002109**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #5** 2011-03-22 12:11**MOT test number** 265181181098**Result** ✓ Passed**Notice** Front pads 1/3rd remaining**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-03-19 13:05**MOT test number** 809918871078**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)**Notice** Front pads 1/3rd remaining**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2010-03-19 14:34
MOT test number	984978870055
Result	✓ Passed
MOT #2	2009-03-17 16:46
MOT test number	514106179031
Result	✓ Passed
MOT #1	2008-03-18 08:34
MOT test number	200578278056
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-05-31
Last registration	2024-01-08
Complete history	See info



Registration #1	2005-05-31	29 mi
Registration #2	2008-03-18	21.172 mi
Registration #3	2009-03-17	28.726 mi
Registration #4	2010-03-19	36.076 mi
Registration #5	2011-03-19	43.304 mi
Registration #6	2011-03-22	43.304 mi
Registration #7	2012-04-14	48.999 mi
Registration #8	2013-03-28	54.337 mi
Registration #9	2014-03-17	59.445 mi
Registration #10	2015-03-18	69.275 mi
Registration #11	2015-03-19	69.276 mi
Registration #12	2016-03-18	75.277 mi
Registration #13	2016-03-19	75.277 mi
Registration #14	2016-03-20	75.277 mi
Registration #15	2016-03-21	75.277 mi
Registration #16	2016-03-22	75.277 mi
Registration #17	2016-03-23	75.277 mi
Registration #18	2016-03-24	75.277 mi
Registration #19	2016-03-25	75.277 mi
Registration #20	2016-03-26	75.277 mi
Registration #21	2016-03-27	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	13030
---------------	-------