



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | EOS SPORT FSI |
| Colour | Black |
| Year of manufacture | 2006 |
| Top speed | 144 mph |
| 0 - 60 mph | 7.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 197 BHP |
| Max. torque | 280 Nm at 5.000 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 24.8 mpg |
| Consumption extra urban | 42.8 mpg |
| Consumption combined | 33.6 mpg |
| CO2 emission | 202 g/km |
| CO2 label | K |



**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2021-06-16 |
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 19 |
| Total items failed | 7 |

MOT #15 2020-06-17 13:26**MOT test number** 692131592019**Result** Passed**Next expiry date** 2021-06-16

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR OF WISHBONE (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR OF WISHBONE (5.3.4 (a) (i))

MOT #14 2019-03-29 16:49**MOT test number** 334476177914**Result** Passed

Advice Engine cover under trays and sill trims fitted

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH sides rear bushes (5.3.4 (a) (i))

**MOT #13**

2019-03-29 11:51

MOT test number

339082480315

Result**✗ Failed****Advice** Brake pad(s) wearing thin ALL pads STONG ADVISE (1.1.13 (a) (ii))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH sides rear bushes (5.3.4 (a) (i))**Advice** Engine cover under trays and sill trims fitted**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm CORDS showing (5.2.3 (e))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #12**

2018-04-05 12:15

MOT test number

212768903554

Result**✓ Passed****Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11**

2018-04-05 11:09

MOT test number

326432853851

Result**✗ Failed**

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #10** 2017-03-27 09:23**MOT test number** 179830659374**Result** ✓ Passed**MOT #9** 2016-04-04 10:08**MOT test number** 927067999868**Result** ✓ Passed**MOT #8** 2015-03-09 13:42**MOT test number** 789108665044**Result** ✓ Passed

Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2014-03-04 14:05**MOT test number** 377273564091**Result** ✓ Passed

Advice Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2013-03-05 10:33**MOT test number** 355594463022**Result** ✓ Passed**MOT #5** 2013-03-05 10:33**MOT test number** 135664663011**Result** ✗ Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



| | |
|---|------------------|
| MOT #4 | 2012-07-25 09:48 |
| MOT test number | 685167202232 |
| Result | ✓ Passed |
| MOT #3 | 2011-07-25 09:01 |
| MOT test number | 127076501210 |
| Result | ✓ Passed |
| MOT #2 | 2010-07-26 10:28 |
| MOT test number | 314427800461 |
| Result | ✓ Passed |
| <div>Notice Offside & nearside front tyres both worn on inside edges.</div> | |
| MOT #1 | 2009-07-27 10:00 |
| MOT test number | 421568509233 |
| Result | ✓ Passed |



Tax & MOT check

✕
Untaxed

Tax expired:
31 October 2020

✕
MOT

Expired:
16 June 2021

| | |
|------------------|---------------------------------|
| Tax status | Expired at 31 October 2020 |
| Days left | 1277 days too late |
| MOT expiry date | 16 June 2021 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  KX06RVT |
| Plate since | 2019-06-29 |
| Current registration |  KX06RVT |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2006-07-25 |
| Last registration | 2020-06-17 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-07-25 | 13 mi |
| Registration #2 | 2009-07-27 | 17.324 mi |
| Registration #3 | 2010-07-26 | 24.252 mi |
| Registration #4 | 2011-07-25 | 29.844 mi |
| Registration #5 | 2012-07-25 | 35.629 mi |
| Registration #6 | 2013-03-05 | 37.710 mi |
| Registration #7 | 2014-03-04 | 41.772 mi |
| Registration #8 | 2015-03-09 | 45.331 mi |
| Registration #9 | 2016-03-09 | 45.331 mi |
| Registration #10 | 2017-03-09 | 45.331 mi |
| Registration #11 | 2018-03-09 | 45.331 mi |
| Registration #12 | 2019-03-09 | 45.331 mi |
| Registration #13 | 2020-03-09 | 45.331 mi |
| Registration #14 | 2021-03-09 | 45.331 mi |
| Registration #15 | 2022-03-09 | 45.331 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1791 mm |
| Height | 1437 mm |
| Length | 4407 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1535 kg |
| Max. allowed weight | 2000 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |

| | |
|-----------------|------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | BWA 083606 |