

Ford



### General information

MakeFORDModelMONDEO TITANIUMColourSilverYear of manufacture2010Top speed144 mph0 - 60 mph7.7 secondsGearbox6 speed automatic		
ColourSilverYear of manufacture2010Top speed144 mph0 - 60 mph7.7 seconds	Make	FORD
Year of manufacture 2010   Top speed 144 mph   0 - 60 mph 7.7 seconds	Model	MONDEO TITANIUM
Top speed 144 mph   0 - 60 mph 7.7 seconds	Colour	Silver
<b>0 - 60 mph</b> 7.7 seconds	Year of manufacture	2010
-	Top speed	144 mph
Gearbox 6 speed automatic	0 - 60 mph	7.7 seconds
	Gearbox	6 speed automatic

# Engine & fuel consumption

Power	200 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.976 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	179 g/km
CO2 label	I







### Internet history

Entry 2 Date

Pictures

2021-07-15

21

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price


2021-07-13 19

View report

source: autotrader.co.uk









# MOT history

MOT expiry date	2024-08-02
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	8
Total items failed	10

MOT #16	2023-07-26 15:40
MOT test number	754945071949
Result	✓ Passed
Next expiry date	2024-08-02

MOT #15	2022-07-26 13:21
MOT test number	584516782857
Result	✓ Passed

MOT #14	2021-07-14 12:12
MOT test number	631961038791
Result	✓ Passed

MOT #13	2021-07-14 12:10
MOT test number	557034052496
Result	🗙 Failed
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #12	2020-08-03 14:10
MOT test number	720829833503
Result	✓ Passed





MOT #11	2020-07-28 12:14	
MOT test number	204154222877	
Result	🗙 Failed	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deterior (g) (i))	ated PIN HOLE (6.1.7	
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))		
<b>Fail</b> Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
FailOffside Front Lower Suspension arm ball joint dust cover no longer prevents the (b) (ii))	ingress of dirt (5.3.4	

MOT #10	2019-07-24 14:07
MOT test number	432777744005
Result	✓ Passed
Advice O/S/FRONT TYRE HAS A CUT ON OUTER WALL WEARING LOW ON INNER EDGE	

MOT #9	2018-07-26 13:51
MOT test number	423730801459
Result	✓ Passed

МОТ #8	2018-07-25 15:53
MOT test number	985151728905
Result	🗙 Failed
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
FailOffside Stop lamp(s) not working (4.3.1 (a) (ii))	



EN10UKF
report date: 2024-03-29

MOT #7	2017-07-26 12:57
MOT test number	665849504461
Result	✓ Passed
Advice O/S/F Tyre sidewall damage	
Advice N/S/F Tyre sidewall damage	

2017-07-25 14:59
120717096533
× Failed
oo high (1.8)
king (1.2.1b)

MOT #5	2016-07-28 16:12
MOT test number	271535569205
Result	✓ Passed

МОТ #4		2016-07-28 16:12
MOT test number		739551679318
Result		🗙 Failed
Pass with rectification	Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #3	2015-07-17 16:46
MOT test number	137908495101
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	





MOT #2	2014-07-11 12:00
MOT test number	118772194150
Result	✓ Passed
MOT #1	2013-07-15 11:11
MOT test number	528176593150
Result	✓ Passed



Tax & MOT check

✓ Taxed	мот
Tax due: 1 July 2024 Tax status	Expires: 2 August 2024 Valid until 1 July
Days left	63
MOT expiry date	2 August 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	F Store
Date	1.E
Category	AMP
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



EN10UKF report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-07-22
Last registration	2023-07-26
Complete history	See info



Registration #1	2010-07-22	6 mi
Registration #2	2013-07-15	31.099 mi
Registration #3	2014-07-11	41.840 mi
Registration #4	2015-07-17	51.737 mi
Registration #5	2016-07-28	60.106 mi
Registration #6	2016-07-28	60.106 mi
Registration #7	2017-07-25	68.253 mi
Registration #8	2017-07-26	68.264 mi
Registration #9	2018-07-25	76.671 mi
Registration #10	2018-07-26	76.677 mi
Registration #11		10.200 mil
-		
Registration #12		11.777 est
Registration #12 Registration #13		11.577 es
-		11.577 est 11.577 est 11.577 est
Registration #13		10.000 est 00.000 est 00.000 est 00.000 est
Registration #13 Registration #14		10.000 est 00.000 est 00.000 est 00.000 est 00.000 est
Registration #13 Registration #14 Registration #15		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #13 Registration #14 Registration #15 Registration #16		10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est





#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

Number of axles CarCheck.co.uk

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1886 mm
Height	1512 mm
Length	4830 mm
Wheel base	2850 mm
Max. allowed weight	2300 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

2

**Engine number** 

AJ03382