



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI
Colour	Black
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





## Internet history

### Entry 7

Date 2021-10-06

Pictures 13

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 6

Date 2021-09-21

Pictures 13

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 5

Date 2021-07-30

Pictures 15

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 4

Date 2021-07-16

CarCheck.co.uk

Pictures

15

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date

2021-07-02

Pictures

15

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date

2021-06-18

Pictures

15

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date

2021-06-03

Pictures

15

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-29
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	50
Total items failed	2

MOT #18	2024-03-23 12:28
MOT test number	551296157276
Result	✓ Passed
Next expiry date	2025-03-29

MOT #17	2023-03-28 07:56
MOT test number	951195085182
Result	✓ Passed

MOT #16	2022-03-21 13:54
MOT test number	997288287620
Result	✓ Passed

**MOT #15**

2021-03-23 15:32

**MOT test number**

532500845820

**Result**

✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured water ingress into lamp unit. (4.4.3 (a))
- Minor** Offside Rear Position lamp light intensity obviously reduced water ingress into lamp unit. (4.2.3 (a) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing top cover. (5.3.2 (b))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Bonnet primary retaining device slightly deteriorated (3.1 (c))
- Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, but not excessively both , heavily lipped. (1.1.14 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #14**

2021-03-23 12:46

**MOT test number**

140709778423

**Result****✗ Failed**

- Advice** Bonnet primary retaining device slightly deteriorated (3.1 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Offside Rear Position lamp light intensity obviously reduced water ingress into lamp unit. (4.2.3 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, but not excessively both , heavily lipped. (1.1.14 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured water ingress into lamp unit. (4.4.3 (a))
- Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing top cover. (5.3.2 (b))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #13**

2020-03-23 09:55

**MOT test number**

287590872068

**Result**

✓ Passed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside reverse light not working.
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing top cover loose. (5.3.2 (b))
- Minor** Offside Rear Position lamp light intensity obviously reduced water ingress into lamp unit. (4.2.3 (a) (i))
- Advice** Front Brake disc worn, but not excessively both, lipped. (1.1.14 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #12**

2019-03-23 12:15

**MOT test number**

341893727006

**Result**

✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Offside Rear Position lamp light intensity obviously reduced lamp unit water contaminated. (4.2.3 (a) (i))
- Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))





## MOT #11

2019-03-23 10:34

## MOT test number

804359902774

## Result

✗ Failed

**Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Rear Nail in tyre**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Rear Position lamp light intensity obviously reduced lamp unit water contaminated. (4.2.3 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

## MOT #10

2018-03-26 14:45

## MOT test number

634903988314

## Result

✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

## MOT #9

2017-03-30 14:22

## MOT test number

494587421525

## Result

✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

## MOT #8

2017-01-05 09:01

## MOT test number

435382765694

## Result

✓ Passed

**Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-01-05 09:01**MOT test number** 171438560153**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-12-22 10:26**MOT test number** 140904133821**Result** ✓ Passed**MOT #5** 2015-12-22 10:26**MOT test number** 933063341156**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2015-01-10 12:44**MOT test number** 499210215087**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #3** 2013-12-27 10:03**MOT test number** 227051063363**Result** ✓ Passed



MOT #2	2012-11-19 12:13
MOT test number	445444322448
Result	✓ Passed
Notice	Child seat fitted in passangers side rear not allowing full inspection of adult seat belt
Notice	Both rear tyres wearing on inner edges

MOT #1	2011-11-21 10:17
MOT test number	697725121356
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
29 March 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	29 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LS58ZKV</b>
Plate since	2019-06-29
Current registration	 <b>LS58ZKV</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >





Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2008-12-22
Last registration	2024-03-23
Complete history	<a href="#">See info</a>



Registration #1	2008-12-22	10 mi
Registration #2	2011-11-21	36.216 mi
Registration #3	2012-11-19	46.375 mi
Registration #4	2013-12-27	53.372 mi
Registration #5	2015-01-10	57.343 mi
Registration #6	2015-12-22	65.720 mi
Registration #7	2015-12-22	65.720 mi
Registration #8	2017-01-05	72.401 mi
Registration #9	2017-01-05	72.401 mi
Registration #10	2017-03-30	74.001 mi
Registration #11	2018-03-26	87.131 mi
Registration #12	2019-03-23	99.318 mi
Registration #13	2019-03-23	99.318 mi
Registration #14	2019-03-23	99.318 mi
Registration #15	2019-03-23	99.318 mi
Registration #16	2019-03-23	99.318 mi
Registration #17	2019-03-23	99.318 mi
Registration #18	2019-03-23	99.318 mi
Registration #19	2019-03-23	99.318 mi
Registration #20	2019-03-23	99.318 mi
Registration #21	2019-03-23	99.318 mi
Registration #22	2019-03-23	99.318 mi
Registration #23	2019-03-23	99.318 mi
Registration #24	2019-03-23	99.318 mi
Registration #25	2019-03-23	99.318 mi
Registration #26	2024-03-23	99.318 mi

**More info** >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Engine number	CBD 300261