





report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 SPORT NAV
Colour	White
Year of manufacture	2016
Top speed	133 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	200 Nm at 4.600 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-28

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-09
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	1

MOT #8		2023-11-03 09:58
MOT test	number	326637171428
Result		✓ Passed
Next expi	ry date	2024-11-09
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #7	2022-11-02 11:12
MOT test number	716216413957
Result	✓ Passed
MOT #6	2021-11-10 12:25
MOT test number	680640952965
Result	✓ Passed
MOT #5	2021-04-14 13:10
MOT test number	815475060453
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-10-02 10:00 **MOT** test number 207257798623 Result × Failed Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Brake disc significantly and obviously worn both rears (1.1.14 (a) (i)) **MAJOR** Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

913936256860

Result

✓ Passed

MOT #1

MOT test number

529329289162

Result

MAJOR Nearside Headlamp aim too high (4.1.2 (a))

MAJOR Nearside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))

MAJOR Offside Headlamp aim too high (4.1.2 (a))

MAJOR Nearside Front Service brake excessively binding (1.2.1 (f))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vahisla slags	40
Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\sim	ner	h:-	L
() \ \ \	ner	nıs	\mathbf{r}

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	UK ZIE
Flate since	
Current registration	OK SIE
Flate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-26
Last registration	2023-11-03
Complete history	See info



Registration #1	2016-09-26	17 mi
Registration #2	2019-09-23	19.741 mi
Registration #3	2019-10-05	19.826 mi
Registration #4	2020-10-02	25.412 mi
Registration #5	2020-10-02	25.412 mi
Registration #6		11.777 ea
Registration #6 Registration #7		11.777 ea 11.777 ea
		11.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1230 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	1000 kg
Max. allowed weight	1260 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	PE 30865366

CarCheck.co.uk page 11/11