




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI TRENDLINE 4MOTION
Colour	White
Year of manufacture	2015
Top speed	101 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.250 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	41.5 mpg
Consumption combined	36.2 mpg
CO2 emission	197 g/km
CO2 label	J






Internet history

Entry 2

Date	2022-08-06
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-08
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-11
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	3
Total items failed	6

MOT #9	2023-10-25 12:12
MOT test number	892950357246
Result	✓ Passed
Next expiry date	2024-11-11
Advice	Central Rear Engine mounting damaged but not to excess gear box mount (6.1.8 (a) (i))

MOT #8	2022-11-07 14:54
MOT test number	684503171849
Result	✓ Passed

MOT #7	2021-11-12 13:27
MOT test number	903949169574
Result	✓ Passed



MOT #6	2021-11-03 16:27
MOT test number	122390520901
Result	✗ Failed
Fail	Offside Front Shock absorbers has negligible damping effect (5.3.2 (d))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))
Fail	Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

MOT #5	2021-02-09 14:58
MOT test number	552151422513
Result	✓ Passed
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #4	2020-01-22 13:37
MOT test number	582450522483
Result	✓ Passed

MOT #3	2020-01-20 10:42
MOT test number	853417954286
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #2	2019-01-15 10:49
MOT test number	672725217485
Result	✓ Passed



MOT #1	2018-02-13 11:51
MOT test number	787503273437
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 December 2024

✓
MOT

Expires:
11 November 2024

Tax status Valid until 1 December

Days left 217

MOT expiry date 11 November 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	BN15KHP
Plate since	2019-09-29
Current registration	BN15KHP
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.
If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.
Download the premium report here and check if this VOLKSWAGEN is financed.

Table with 2 columns: Field Name (Finance company, Date of agreement, Agreement type, Agreement term, Agreement number, Contact info) and Value (blurred).

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-26
Last registration	2023-10-25
Complete history	See info



Registration #1	2015-03-26	14 mi
Registration #2	2018-02-13	52.245 mi
Registration #3	2019-01-15	68.530 mi
Registration #4	2020-01-20	85.224 mi
Registration #5	2020-01-22	85.225 mi
Registration #6	2021-02-09	105.572 mi
Registration #7	2022-02-09	105.572 mi
Registration #8	2022-02-09	105.572 mi
Registration #9	2022-02-09	105.572 mi
Registration #10	2022-02-09	105.572 mi
Registration #11	2022-02-09	105.572 mi
Registration #12	2022-02-09	105.572 mi

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	CNFB052992