



report date: 2024-03-28

General information

Make	MINI
Model	PACEMAN COOPER D ALL4
Colour	Silver
Year of manufacture	2016
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D






Internet history

Entry 1

Date	2022-02-15
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-12
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	10
Total items failed	5

MOT #7 2024-01-02 12:21

MOT test number 402997022931

Result ✓ Passed

Next expiry date 2025-01-12

Advice Nearside Rear Brake pipe corroded, covered in grease or other material Pipe is swollen under the coating (1.1.11 (c))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material Pipe is swollen under the coating (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material Pipe is swollen under the coating (1.1.11 (c))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material Pipe is swollen under the coating (1.1.11 (c))

MOT #6 2023-12-27 13:27

MOT test number 309840381338

Result ✗ Failed

Fail Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

Advice Offside Rear Nail in tyre

Fail Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

**MOT #5** 2023-01-13 15:32**MOT test number** 214924097442**Result** ✓ Passed**MOT #4** 2023-01-10 09:16**MOT test number** 277410612169**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2021-12-02 11:48**MOT test number** 943149149011**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front and rear (5.2.3 (e))**Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**MOT #2** 2020-12-12 08:55**MOT test number** 701865421147**Result** ✓ Passed**MOT #1** 2019-12-14 10:15**MOT test number** 226099465188**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
12 January 2025

Tax status	Valid until 1 December
Days left	215
MOT expiry date	12 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-12-31
Last registration	2024-01-02
Complete history	See info



Registration #1	2016-12-31	9 mi
Registration #2	2019-12-14	21.132 mi
Registration #3	2020-12-12	28.571 mi
Registration #4	2021-12-02	33.084 mi
Registration #5	2022-01-01	35.000 mi
Registration #6	2022-01-01	35.000 mi
Registration #7	2022-01-01	35.000 mi
Registration #8	2022-01-01	35.000 mi
Registration #9	2022-01-01	35.000 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1518 mm
Length	4109 mm
Wheel base	2596 mm
Kerb weight	1370 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	73289674