



PEUGEOT



BG5IMFV

report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 HDI LX
Colour	Silver
Year of manufacture	2001
Top speed	99 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	150 Nm at 1.750 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.3 mpg
Consumption extra urban	70.5 mpg
Consumption combined	62.7 mpg
CO2 emission	120 g/km
CO2 label	C





MOT history

MOT expiry date	2021-01-31
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	37
Total items failed	13

MOT #21	2020-02-01 16:42
MOT test number	120635838679
Result	✓ Passed
Next expiry date	2021-01-31
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Osf lower arm rear bush deteriorated
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2020-02-01 14:44

MOT test number

542395684323

Result**✗ Failed**

- Advice** Osf lower arm rear bush deteriorated
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Headlamp are incorrectly positioned (4.1.4 (a))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #19

2018-09-26 15:58

MOT test number

514271180388

Result**✓ Passed**

- Advice** Offside Front Steering arm deformed but serviceable inner joint (2.1.3 (c) (i))

MOT #18

2018-09-17 17:32

MOT test number

304694218926

Result**✗ Failed**

- MAJOR** Nearside Rear Exhaust has a major leak of exhaust gases box (6.1.2 (a))
- MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Steering arm deformed but serviceable inner joint (2.1.3 (c) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2017-09-20 09:01

MOT test number

866311379877

Result

✓ Passed

Advice Offside Front Body has slight corrosion jacking point (6.1.B.2)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Front Oil leak engine**MOT #16**

2017-09-18 16:40

MOT test number

155405257738

Result

✗ Failed

Fail Central Rear Exhaust has a major leak of exhaust gases box (7.1.2)**Advice** Offside Front Oil leak engine**Advice** Offside Front Body has slight corrosion jacking point (6.1.B.2)**Fail** Central Rear Stop lamp not working (1.2.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #15**

2016-10-20 15:22

MOT test number

848986880650

Result

✓ Passed

MOT #14

2015-05-30 11:09

MOT test number

326030655127

Result

✓ Passed

Advice Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #13** 2014-06-03 13:02**MOT test number** 989114254171**Result** ✓ Passed**MOT #12** 2014-06-02 14:34**MOT test number** 159693854118**Result** ✗ Failed

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

Fail Nearside Rear position lamp(s) not working (1.1.A.3b)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #11 2013-06-18 13:04**MOT test number** 515139363123**Result** ✓ Passed**MOT #10** 2013-06-10 11:55**MOT test number** 319221063186**Result** ✗ Failed

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

MOT #9 2012-06-11 10:03**MOT test number** 328443962108**Result** ✓ Passed

Notice Air bag light on

**MOT #8** 2012-06-11 10:03**MOT test number** 877353662144**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Air bag light on**MOT #7** 2011-06-17 10:55**MOT test number** 795568761136**Result** ✓ Passed**MOT #6** 2010-06-19 15:47**MOT test number** 621180770149**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-06-19 13:03**MOT test number** 344940470182**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2009-06-18 12:09**MOT test number** 481609469106**Result** ✓ Passed**Advice** Rear brake disc slightly pitted (3.5.1h)



MOT #3	2008-04-04 12:01
MOT test number	930175698002
Result	✓ Passed
Advice	Offside Rear brake disc slightly scored (3.5.1h)
Advice	Nearside Rear brake disc slightly scored (3.5.1h)

MOT #2	2007-01-31 10:12
MOT test number	991661037082
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2006-01-17 10:53
MOT test number	981347016007
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
9 November 2020

X

MOT

Expired:
31 January 2021

Tax status	Expired at 9 November 2020
Days left	1267 days too late
MOT expiry date	31 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2001-11-02
Last registration	2020-02-01
Complete history	See info



Registration #1	2001-11-02	16 mi
Registration #2	2006-01-17	34.446 mi
Registration #3	2007-01-31	39.480 mi
Registration #4	2008-04-04	49.901 mi
Registration #5	2009-06-18	52.411 mi
Registration #6	2010-06-19	57.624 mi
Registration #7	2010-06-19	57.624 mi
Registration #8	2011-06-17	62.740 mi
Registration #9	2012-06-11	67.868 mi
Registration #10	2013-06-10	73.501 mi
Registration #11	2013-06-18	73.501 mi
Registration #12	2014-06-18	73.501 mi
Registration #13	2015-06-18	73.501 mi
Registration #14	2016-06-18	73.501 mi
Registration #15	2017-06-18	73.501 mi
Registration #16	2018-06-18	73.501 mi
Registration #17	2019-06-18	73.501 mi
Registration #18	2020-02-01	73.501 mi
Registration #19	2020-02-01	73.501 mi
Registration #20	2020-02-01	73.501 mi
Registration #21	2020-02-01	73.501 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1179 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	FD010008292