



HYUNDAI




report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | HYUNDAI |
| Model | TERRACAN CRTD CDX |
| Colour | Silver |
| Year of manufacture | 2004 |
| Top speed | 104 mph |
| 0 - 60 mph | 13.4 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 333 Nm at 2.000 rpm |
| Engine capacity | 2.902 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 22.4 mpg |
| Consumption extra urban | 34.5 mpg |
| Consumption combined | 28.8 mpg |
| CO2 emission | 241 g/km |
| CO2 label | L |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-07 |
| Pictures | 17 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-20 |
| MOT pass rate | 71 % |
| MOT passed | 17 |
| Failed MOT tests | 7 |
| Total advice items | 40 |
| Total items failed | 10 |

MOT #24 2023-09-21 08:20

MOT test number 353478495738

Result ✓ Passed

Next expiry date 2024-09-20

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 225/65-16 (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #23 2023-09-15 14:27

MOT test number 158573788172

Result ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 225/65-16 (5.2.3 (d) (ii))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #22** 2022-03-17 09:39**MOT test number** 222054973743**Result** ✓ Passed**MOT #21** 2022-03-17 09:39**MOT test number** 209349870844**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #20** 2021-10-25 15:13**MOT test number** 526931030689**Result** ✓ Passed**MOT #19** 2020-11-24 12:49**MOT test number** 281715659967**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #18** 2019-05-23 14:09**MOT test number** 605192243268**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Spare tyre defective
- Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

MOT #17 2018-05-18 16:29**MOT test number** 882147885751**Result** ✓ Passed**MOT #16** 2017-05-16 15:32**MOT test number** 909542281347**Result** ✓ Passed**MOT #15** 2016-05-04 14:43**MOT test number** 988936070752**Result** ✓ Passed**MOT #14** 2015-05-07 11:21**MOT test number** 178107925198**Result** ✓ Passed

- Notice** N/s/r tyre at 3.1mm
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #13** 2014-05-28 14:17**MOT test number** 757728244185**Result** ✓ Passed**MOT #12** 2013-12-18 09:50**MOT test number** 468502653315**Result** ✓ Passed**MOT #11** 2013-12-16 10:52**MOT test number** 116250453360**Result** ✗ Failed**Advice** Inner Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10** 2012-08-16 15:55**MOT test number** 515079222225**Result** ✓ Passed**Notice** 255/65/16 both front tyres unevenly worn on inner edges advise alignment check**MOT #9** 2012-08-16 15:55**MOT test number** 325939622236**Result** ✗ Failed**Pass with rectification** Headlamp aim too high and too far to the right. (1.8)**Notice** 255/65/16 both front tyres unevenly worn on inner edges advise alignment check

**MOT #8** 2011-08-23 15:06**MOT test number** 775755631226**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2011-08-23 14:51**MOT test number** 728635231249**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2010-10-05 16:47**MOT test number** 302148770204**Result** ✓ Passed**MOT #5** 2009-10-06 13:44**MOT test number** 392729979272**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-10-06 13:44**MOT test number** 380629479233**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|---|
| MOT #3 | 2008-08-12 17:09 |
| MOT test number | 411535128251 |
| Result | ✓ Passed |
| Advice | Offside Front Brake pad(s) wearing thin (3.5.1g) |
| Advice | Offside Rear brake disc slightly pitted (3.5.1h) |
| Advice | Nearside Front Brake pad(s) wearing thin (3.5.1g) |
| Advice | Nearside Rear brake disc slightly pitted (3.5.1h) |

| | |
|-------------------------|---|
| MOT #2 | 2008-08-12 17:09 |
| MOT test number | 821515628251 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Advice | Nearside Front Brake pad(s) wearing thin (3.5.1g) |
| Advice | Nearside Rear brake disc slightly pitted (3.5.1h) |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Advice | Offside Front Brake pad(s) wearing thin (3.5.1g) |
| Advice | Offside Rear brake disc slightly pitted (3.5.1h) |

| | |
|-----------------|------------------|
| MOT #1 | 2007-08-31 15:04 |
| MOT test number | 171873947263 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
20 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 155 |
| MOT expiry date | 20 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 23 |
| First mileage registration | 2004-07-27 |
| Last registration | 2023-09-21 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2004-07-27 | 15 mi |
| Registration #2 | 2007-08-31 | 39.339 mi |
| Registration #3 | 2008-08-12 | 48.317 mi |
| Registration #4 | 2009-10-06 | 58.802 mi |
| Registration #5 | 2010-10-05 | 67.829 mi |
| Registration #6 | 2011-08-23 | 71.844 mi |
| Registration #7 | 2011-08-23 | 71.844 mi |
| Registration #8 | 2012-08-16 | 83.016 mi |
| Registration #9 | 2013-12-16 | 90.138 mi |
| Registration #10 | 2013-12-18 | 90.139 mi |
| Registration #11 | 2014-05-28 | 91.306 mi |
| Registration #12 | 2015-05-07 | 93.734 mi |
| Registration #13 | 2015-05-07 | 93.734 mi |
| Registration #14 | 2015-05-07 | 93.734 mi |
| Registration #15 | 2015-05-07 | 93.734 mi |
| Registration #16 | 2015-05-07 | 93.734 mi |
| Registration #17 | 2015-05-07 | 93.734 mi |
| Registration #18 | 2015-05-07 | 93.734 mi |
| Registration #19 | 2015-05-07 | 93.734 mi |
| Registration #20 | 2015-05-07 | 93.734 mi |
| Registration #21 | 2015-05-07 | 93.734 mi |
| Registration #22 | 2015-05-07 | 93.734 mi |
| Registration #23 | 2015-05-07 | 93.734 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1860 mm |
| Height | 1840 mm |
| Length | 4710 mm |
| Wheel base | 2750 mm |
| Kerb weight | 2255 kg |
| Max. allowed weight | 2650 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 75 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | J3871298 |