



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D3 R-DESIGN
Colour	Black
Year of manufacture	2011
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 3

Date 2021-07-05

Pictures 17

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2021-06-19

Pictures 17

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-06-03

Pictures 17

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	28
Total items failed	12

MOT #14	2024-04-03 14:33
MOT test number	104774544330
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-03-22 15:17
MOT test number	167076522860
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT (1.1.14 (a) (ii))
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge INNER EDGE CLOSE ADVISE REPLACE (5.2.3 (e))

**MOT #12**

2023-03-22 09:02

MOT test number

605057315400

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Headlamp insecure (4.1.1 (c))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT (1.1.14 (a) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge INNER EDGE CLOSE ADVISE REPLACE (5.2.3 (e))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #11

2022-04-13 12:42

MOT test number

260965952853

Result**✓ Passed**

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10

2021-03-10 11:43

MOT test number

619006180131

Result**✓ Passed****MOT #9**

2020-03-17 13:55

MOT test number

520666142293

Result**✓ Passed**

- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2020-03-17 12:14**MOT test number** 944977979256**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2019-03-15 11:17**MOT test number** 977870186669**Result** ✓ Passed**Advice** Under tray(s) fitted to vehicle**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both rear shockers weak**MOT #6** 2018-03-27 13:05**MOT test number** 965271119209**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2018-03-26 13:16**MOT test number** 430805032278**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2017-03-15 11:57**MOT test number** 932978651817**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-03-22 12:04**MOT test number** 526085751445**Result** ✓ Passed**MOT #2** 2016-03-22 12:04**MOT test number** 641559116101**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #1** 2015-03-28 14:46**MOT test number** 717527785076**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Emissions low count



Tax & MOT check

X

Untaxed

Tax expired:
27 March 2024

✓

MOT

Expires:
12 April 2025

Tax status	Expired at 27 March 2024
Days left	34 days too late
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-11-16
Last registration	2024-04-03
Complete history	See info



Registration #1	2011-11-16	9 mi
Registration #2	2015-03-28	88.272 mi
Registration #3	2016-03-22	95.776 mi
Registration #4	2016-03-22	95.776 mi
Registration #5	2017-03-15	100.265 mi
Registration #6	2018-03-26	104.721 mi
Registration #7	2018-03-27	104.722 mi
Registration #8	2019-03-15	110.298 mi
Registration #9	2020-03-17	114.849 mi
Registration #10	2020-03-22	115.377 mi
Registration #11	2020-03-22	115.377 mi
Registration #12	2020-03-22	115.377 mi
Registration #13	2020-03-22	115.377 mi
Registration #14	2020-03-22	115.377 mi
Registration #15	2020-03-22	115.377 mi
Registration #16	2020-03-22	115.377 mi
Registration #17	2020-03-22	115.377 mi
Registration #18	2020-03-22	115.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1648 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

1006072