





### General information

Make	ΤΟΥΟΤΑ
Model	COROLLA VALVEMATIC TR
Colour	Blue
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

## Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G







### Internet history

Entry 1

Date Pictures 2021-02-05

6

Listing price

View report









source: autoonline.co.uk



# MOT history

MOT expiry date	2024-11-25
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	38
Total items failed	6

MOT #17	2023-11-25 12:05
MOT test number	387829261767
Result	🗸 Passed
Next expiry date 202	
Advice Undercover fitted obscuring some components	
Advice Tyre both side won	

MOT #16		2022-11-26 12:38
MOT test	number	637574799638
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened $(1.1.14$ (a) (ii)	)
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	





MOT #15	2022-11-26 12:38
MOT test number	794592805193
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Pass with rectification</b> Headlamp aim too low Both sides (4.1.2 (a))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	

MOT #14		2021-11-23 14:49
MOT test	number	832532136339
Result		✓ Passed
Advice	Undercover fitted obscuring some components	
Advice	Rear Brake pad(s) wearing thin both rear (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, but not excessively both rear (1.1.14 (a) (i))	

MOT #13		2021-11-23 14:49
MOT test number		998340818552
Result		🗙 Failed
Pass with rectification	Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))	
Advice Undercover fitte	d obscuring some components	
Advice Rear Brake disc	worn, but not excessively both rear (1.1.14 (a) (i))	
Advice Rear Brake pad(	s) wearing thin both rear (1.1.13 (a) (ii))	





MOT #12		2020-10-19 07:36
MOT test	number	451480225160
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MOT #11		2019-10-21 09:54
MOT test	number	491221234846
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edge and	d cracking (5.2.3 (e))

MOT #10	2018-10-17 14:27
MOT test	number 662365417642
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge of tread (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9		2017-09-29 15:19
MOT test	number	915020075955
Result		✓ Passed
Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear view	(8.1.2a)
Advice	Nearside Rear Nail in tyre outer edge of tread	



MOT #8	2017-09-29 09:45	
MOT test number	986305358900	
Result	🗙 Failed	
<b>Fail</b> Nearside Rear position lamp(s) not working (1.1.A.3b)		
Advice Nearside Rear Nail in tyre outer edge of tread		
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall 205/60/R16 H (4.1.D.1b)		
Advice Offside Obligatory mirror damaged, but not seriously affecting the rear v	iew (8.1.2a)	

MOT #7		2016-10-22 08:22
MOT test	number	440596234928
Result		✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt fitted to all rear seat's	
Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1	2a)

MOT #6		2016-10-21 13:54
MOT test	number	133706007539
Result		🗙 Failed
Advice	Child Seat fitted not allowing full inspection of adult belt fitted to all rear seat's	
Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.	2a)
Advice	Offside Front tyre wearing smooth inner edge	
<b>Fail</b> N	earside Front Tyre has ply or cords exposed inner edge 205/60/R16 (4.1.D.1b)	

MOT #5	2015-10-23 08:13
MOT test number	649816268277
Result	✓ Passed
Advice Offside side mirror clover slight damage	

**RK10TKV** 

report date: 2024-03-29





MOT #4		2015-10-23 08:13
MOT test number		617532210614
Result		× Failed
Advice Offside side mirr	or clover slight damage	
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (8.	2.2)
MOT #3		2015-02-13 10:48
MOT test number		327914245018
Result		🗸 Passed

MOT #2		2014-02-28 10:23
MOT test	number	395019654035
Result		Passed
Notice	Offside front tyre cut across trea not deep enough to reach ply or cord's	
Notice	Offside mirror damaged	
Notice	Under-trays fitted obscuring some underside components	

MOT #1	2013-03-15 11:13
MOT test number	727094173091
Result	✓ Passed



RK10TKV report date: 2024-03-29

Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 April 2025 Tax status	25 November 2024 Valid until 1 April
Days left	336
MOT expiry date	25 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10 700





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
***********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-18
Last registration	2023-11-25
Complete history	See info



Registration #1	2010-03-18	24 mi
Registration #2	2013-03-15	18.509 mi
Registration #3	2014-02-28	29.888 mi
Registration #4	2015-02-13	40.670 mi
Registration #5	2015-10-23	46.341 mi
Registration #6	2015-10-23	46.341 mi
Registration #7	2016-10-21	57.183 mi
Registration #8	2016-10-22	57.186 mi
Registration #9	2017-09-29	64.668 mi
Registration #10	2017-09-29	64.669 mi
Registration #10 Registration #11	2017-09-29	64.669 mi
-	2017-09-29	64.669 mi
Registration #11	2017-09-29	64.669 mi
Registration #11 Registration #12	2017-09-29	64.669 mi
Registration #11 Registration #12 Registration #13	2017-09-29	64.669 mi
Registration #11 Registration #12 Registration #13 Registration #14	2017-09-29	64.669 mi
Registration #11Registration #12Registration #13Registration #14Registration #15	2017-09-29	64.669 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2017-09-29	64.669 mi





## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

Number of axles

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg
Additional information	
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

2