



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	URBAN CRUISER VVT-I
Colour	Purple
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.329 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 2

Date	2022-11-09
Pictures	15
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-04
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-30
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	24
Total items failed	14

## MOT #22 2023-12-01 17:41

MOT test number 533689446879

Result ✓ Passed

Next expiry date 2024-11-30

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened O/S N/S (1.1.14 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge O/S N/S (5.2.3 (e))

## MOT #21 2022-11-07 15:16

MOT test number 499204131074

Result ✓ Passed

## MOT #20 2022-11-03 16:56

MOT test number 296042392270

Result ✗ Failed**Fail** Front Registration plate inscription illegible (0.1 (b))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

## MOT #19 2021-11-30 14:01

MOT test number 698238618500

Result ✓ Passed

**MOT #18**

2021-05-28 09:03

**MOT test number**

484316246439

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #17**

2021-05-26 12:20

**MOT test number**

494860471777

**Result**

✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 1956016 (5.2.3 (e))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #16**

2020-07-07 08:34

**MOT test number**

514447476639

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2019-05-15 09:42

**MOT test number**

859954950279

**Result**

✓ Passed

**Advice** Both rear tyres have some age cracks**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #14**

2019-05-15 09:42

**MOT test number**

788355864279

**Result**

✗ Failed

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Both rear tyres have some age cracks**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #13**

2018-05-17 13:32

**MOT test number**

873611471741

**Result**

✓ Passed

**MOT #12**

2017-06-27 15:18

**MOT test number**

882326909506

**Result**

✓ Passed

**MOT #11** 2017-06-27 09:53**MOT test number** 545033011222**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10** 2016-07-07 09:20**MOT test number** 785422943255**Result** ✓ Passed**MOT #9** 2016-07-07 09:20**MOT test number** 823318245112**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2015-07-06 08:07**MOT test number** 437597385142**Result** ✓ Passed**MOT #7** 2015-07-03 08:54**MOT test number** 387994285119**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-07-07 11:49**MOT test number** 125918084136**Result** ✓ Passed**MOT #5** 2013-10-08 13:54**MOT test number** 238911983202**Result** ✓ Passed**MOT #4** 2013-10-07 15:33**MOT test number** 367890383227**Result** ✗ Failed

**Fail** Nearside Front Tyre(s) incorrect because tyres with different aspect ratios are fitted on the same axle. (4.1.A.1a)

**MOT #3** 2013-07-12 13:02**MOT test number** 216443093103**Result** ✓ Passed

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Front discs corroded on inner faces

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2012-08-09 13:11**MOT test number** 356332822435**Result** ✓ Passed**MOT #1** 2012-07-30 14:55**MOT test number** 757902412245**Result** ✗ Failed

**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
30 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	30 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>DA09WZC</b>
Plate since	2024-03-29
Current registration	<b>DA09WZC</b>
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2009-08-15
Last registration	2023-12-01
Complete history	<a href="#">See info</a>



Registration #1	2009-08-15	21 mi
Registration #2	2012-07-30	43.276 mi
Registration #3	2012-08-09	43.507 mi
Registration #4	2013-07-12	58.062 mi
Registration #5	2013-10-07	61.631 mi
Registration #6	2013-10-08	61.631 mi
Registration #7	2014-07-07	69.674 mi
Registration #8	2015-07-03	81.087 mi
Registration #9	2015-07-06	81.489 mi
Registration #10	2016-07-07	92.214 mi
Registration #11	2016-07-07	92.214 mi
Registration #12	2017-06-27	104.144 mi
Registration #13	2017-06-27	104.144 mi
Registration #14	2018-06-27	115.144 mi
Registration #15	2018-06-27	115.144 mi
Registration #16	2018-06-27	115.144 mi
Registration #17	2018-06-27	115.144 mi
Registration #18	2018-06-27	115.144 mi
Registration #19	2018-06-27	115.144 mi
Registration #20	2018-06-27	115.144 mi
Registration #21	2018-06-27	115.144 mi
Registration #22	2018-06-27	115.144 mi
Registration #23	2018-06-27	115.144 mi
Registration #24	2018-06-27	115.144 mi
Registration #25	2018-06-27	115.144 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1725 mm
Height	1525 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1150 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1NR0052935