



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LX
Colour	Red
Year of manufacture	2003
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.2 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-24
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-25
MOT pass rate	86 %
MOT passed	19
Failed MOT tests	3
Total advice items	30
Total items failed	15

MOT #22	2023-08-09 10:05
MOT test number	105912578668
Result	✓ Passed
Next expiry date	2024-08-25
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Rear service brake and parking brake efficiency just met requires attention

MOT #21	2022-08-26 12:56
MOT test number	121151075654
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Items removed from driver's view prior to test
Advice	Brake load sensing valve stiff (1.1.17 (c) (i))
Advice	Play in steering rack inner joint(s)

**MOT #20**

2022-08-26 12:56

**MOT test number**

509712177036

**Result****✗ Failed****Advice** Items removed from driver's view prior to test**Pass with rectification** Offside Rear Tyre(s) with different structures are fitted across the same axle (5.2.3 (c))**Advice** Brake load sensing valve stiff (1.1.17 (c) (i))**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #19**

2021-07-26 12:55

**MOT test number**

747064492069

**Result****✓ Passed****Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Windscreen wiper blade defective (3.4 (b) (i))**MOT #18**

2020-12-10 15:21

**MOT test number**

464702259197

**Result****✓ Passed****Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Forward and rear bushes perished/split (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Forward and rear bushes perished/split (5.3.4 (a) (i))

**MOT #17**

2020-12-07 09:59

**MOT test number**

972459314958

**Result****✗ Failed**

- Fail** Rear Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Forward and rear bushes perished/split (5.3.4 (a) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Forward and rear bushes perished/split (5.3.4 (a) (i))
- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #16**

2019-12-11 12:40

**MOT test number**

567780001600

**Result****✓ Passed**

- Advice** Offside Front tyre worn on edges bald on inner edge
- Advice** Nearside Front tyre bald on edges and perished

**MOT #15** 2019-12-10 16:39**MOT test number** 843261928089**Result** ✗ Failed**Advice** Offside Front tyre worn on edges bald on inner edge**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**Advice** Nearside Front tyre bald on edges and perished**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Fail** Nearside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**MOT #14** 2018-12-13 12:02**MOT test number** 958158819833**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #13** 2017-12-15 13:00**MOT test number** 436571211510**Result** ✓ Passed**Advice** Two rear tyres slightly perished**Advice** Nearside Front Suspension arm has slight play in a ball joint lower ball joint (2.4.G.2)**MOT #12** 2016-11-30 11:10**MOT test number** 718817452351**Result** ✓ Passed**Advice** Engine has an oil leak from the front**Advice** Offside Rear Tyre is perishing on the sidewalls (inside)



<b>MOT #11</b>	2015-12-11 12:28
<b>MOT test number</b>	689256931104
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)
<b>MOT #10</b>	2014-12-08 10:56
<b>MOT test number</b>	255482744346
<b>Result</b>	✓ Passed
<b>MOT #9</b>	2013-12-09 11:22
<b>MOT test number</b>	916423243367
<b>Result</b>	✓ Passed
<b>Notice</b>	Both front tyres low on tread on edges, rear tyres staring to perish on sidewall
<b>MOT #8</b>	2012-12-10 12:11
<b>MOT test number</b>	297525842321
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2011-12-02 10:37
<b>MOT test number</b>	429146231442
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2010-12-06 11:31
<b>MOT test number</b>	363430940321
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2009-12-17 11:23
<b>MOT test number</b>	624561559306
<b>Result</b>	✓ Passed



MOT #4	2008-12-09 11:13
MOT test number	400334448479
Result	✓ Passed
MOT #3	2007-12-07 11:53
MOT test number	950511347395
Result	✓ Passed
MOT #2	2006-12-07 11:52
MOT test number	272951546368
Result	✓ Passed
MOT #1	2005-12-12 12:12
MOT test number	143366745320
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
25 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	25 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>WM52FTX</b>
Plate since	2024-03-29
Current registration	<b>WM52FTX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-02-12
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2003-02-12	10 mi
Registration #2	2005-12-12	18.264 mi
Registration #3	2006-12-07	26.749 mi
Registration #4	2007-12-07	33.334 mi
Registration #5	2008-12-09	41.176 mi
Registration #6	2009-12-17	50.686 mi
Registration #7	2010-12-06	55.742 mi
Registration #8	2011-12-02	61.205 mi
Registration #9	2012-12-10	66.214 mi
Registration #10	2013-12-09	69.577 mi
Registration #11	2014-12-08	74.210 mi
Registration #12	2015-12-11	78.103 mi
Registration #13	2016-12-10	82.000 mi
Registration #14	2017-12-09	85.900 mi
Registration #15	2018-12-08	89.800 mi
Registration #16	2019-12-07	93.700 mi
Registration #17	2020-12-06	97.600 mi
Registration #18	2021-12-05	101.500 mi
Registration #19	2022-12-04	105.400 mi
Registration #20	2023-02-03	109.300 mi
Registration #21	2023-04-02	113.200 mi
Registration #22	2023-06-01	117.100 mi
Registration #23	2023-08-09	121.000 mi
Registration #24	2023-10-08	124.900 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	FSJ24469875