



report date: 2024-03-28

## General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-02-03
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-10-04
<b>MOT pass rate</b>	83 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	23
<b>Total items failed</b>	3

**MOT #12** 2023-09-28 10:52**MOT test number** 153566403313**Result** Passed**Next expiry date** 2024-10-04

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #11** 2022-10-05 10:19**MOT test number** 353623540690**Result** Passed

- Advice** Rear tyres wearing thin
- Advice** Front tyres wearing thin/worn on edges
- Advice** Undertrays fitted restricting inspection

**MOT #10**

2022-10-05 10:19

**MOT test number**

866584203334

**Result**

✗ Failed

**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear tyres wearing thin**Advice** Front tyres wearing thin/worn on edges**Advice** Undertrays fitted restricting inspection**MOT #9**

2021-12-09 10:58

**MOT test number**

434974027200

**Result**

✓ Passed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge Edge is going bald (5.2.3 (e))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Edge is going bald (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8**

2020-12-11 10:16

**MOT test number**

830180663184

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened corroding (1.1.14 (a) (ii))**MOT #7**

2020-02-05 09:31

**MOT test number**

298287388904

**Result**

✓ Passed

**MOT #6** 2019-09-04 10:01**MOT test number** 807519333340**Result** ✓ Passed**Advice** Rear Lower Coil spring corroded both sides (5.3.1 (b) (i))**Advice** Front engine and floor trims fitted**MOT #5** 2018-09-04 10:25**MOT test number** 982170036268**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2017-08-29 13:01**MOT test number** 949926679555**Result** ✓ Passed**Advice** Emissions too lean to record**Advice** Offside Front Tyre worn close to the legal limit bald inside edge (4.1.E.1)**Advice** Nearside Front Inner Tyre worn close to the legal limit bald inner edge (4.1.E.1)**MOT #3** 2016-09-07 12:51**MOT test number** 394429860472**Result** ✓ Passed**MOT #2** 2016-08-31 15:20**MOT test number** 482280158857**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)



MOT #1	2015-07-15 13:32
MOT test number	635746195154
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
4 October 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	4 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>RJ12SKZ</b>
Plate since	2024-03-28
Current registration	<b>RJ12SKZ</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-08-01
Last registration	2023-09-28
Complete history	<a href="#">See info</a>



Registration #1	2012-08-01	19 mi
Registration #2	2015-07-15	45.505 mi
Registration #3	2016-08-31	65.628 mi
Registration #4	2016-09-07	65.752 mi
Registration #5	2017-08-29	84.407 mi
Registration #6	2018-09-04	102.997 mi
Registration #7	2019-09-04	127.579 mi
Registration #8	2020-09-04	152.161 mi
Registration #9	2021-09-04	176.743 mi
Registration #10	2022-09-04	201.325 mi
Registration #11	2023-09-04	225.907 mi
Registration #12	2024-03-28	250.489 mi
Registration #13	2024-03-28	275.071 mi
Registration #14	2024-03-28	299.653 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1802 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1516 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1220500