



CITROËN



CK08KCC


report date: 2024-03-29

## General information

Make	CITROEN
Model	C5 VTR HDI
Colour	Silver
Year of manufacture	2008
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-27
Pictures	16
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-07-12
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	49
Total items failed	10

MOT #19	2021-07-13 09:01
MOT test number	736691626633
Result	✓ Passed
Next expiry date	2022-07-12

MOT #18	2020-12-11 09:48
MOT test number	634346893004

Result	✓ Passed
--------	----------

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Direction indicator slightly discoloured nearside and offside (4.4.3 (a))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** All 4 suspension units are slightly damp

**MOT #17** 2020-12-11 09:48**MOT test number** 481018110176**Result** ✗ Failed**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** All 4 suspension units are slightly damp**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Direction indicator slightly discoloured nearside and offside (4.4.3 (a))**MOT #16** 2019-05-30 11:32**MOT test number** 372865899559**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** All 4 suspension units are leaking slightly**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #15** 2018-06-22 06:06**MOT test number** 192676327142**Result** ✓ Passed**MOT #14** 2018-03-15 15:31**MOT test number** 880852008649**Result** ✓ Passed

**MOT #13** 2017-03-16 15:25**MOT test number** 797065654616**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** N/S/R wheel slight binding**MOT #12** 2017-03-14 09:35**MOT test number** 362844556744**Result** ✗ Failed**Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)**Advice** N/S/R wheel slight binding**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-03-21 10:22**MOT test number** 825620069051**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 2.70mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 3.0mm (4.1.E.1)**Advice** Engine & under covers fitted to vehicle.

**MOT #10**

2016-03-18 11:52

**MOT test number**

554407164727

**Result**

✗ Failed

- Advice** Nearside Brake pad(s) wearing thin (3.5.1g)
- Advice** Thorn in sidewall n/s/f tyre.
- Advice** Offside Rear Tyre worn close to the legal limit 2.70mm (4.1.E.1)
- Advice** Engine & under covers fitted to vehicle.
- Fail** Front brake application uneven (3.7.B.2)
- Advice** Nearside Rear Tyre worn close to the legal limit 3.0mm (4.1.E.1)
- Advice** Front brake discs corroded on inner surfaces.
- Fail** Front parking (secondary) brakes imbalanced (3.7.B.6b)

**MOT #9**

2015-03-17 12:12

**MOT test number**

148426175026

**Result**

✓ Passed

- Notice** Both rear tyre tread wearing uneven on inside edge
- Advice** Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)
- Notice** Rear bump stops worn
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #8	2015-03-17 12:12
MOT test number	967746175079
Result	✗ Failed
Notice	Rear bump stops worn
Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Notice	Both rear tyre tread wearing uneven on inside edge
Advice	Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

MOT #7	2014-03-20 12:27
MOT test number	956479874074
Result	✓ Passed
Notice	Rear bump stops worn
Advice	Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
Notice	Both rear tyre tread wearing uneven on inside edge
Advice	Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
Advice	Offside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

**MOT #6** 2014-03-19 13:10**MOT test number** 476758274006**Result** ✗ Failed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)**Notice** Rear bump stops worn**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**Notice** Both rear tyre tread wearing uneven on inside edge**Fail** Offside Inner Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #5** 2013-03-14 16:13**MOT test number** 919363573006**Result** ✓ Passed**MOT #4** 2013-03-14 16:13**MOT test number** 346613673074**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2012-03-21 12:29**MOT test number** 357111382043**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components





MOT #2	2012-03-21 12:29
MOT test number	147251882053
Result	✗ Failed
Pass with rectification	Rear registration plate character(s) likely to be misread (6.3.4b)
Notice	Under-trays fitted obscuring some underside components
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-02-23 11:24
MOT test number	488294951017
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
25 March 2022

✕  
MOT

Expired:  
12 July 2022

Tax status	Expired at 25 March 2022
Days left	766 days too late
MOT expiry date	12 July 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-21
Last registration	2021-07-13
Complete history	<a href="#">See info</a>



Registration #1	2008-03-21	12 mi
Registration #2	2011-02-23	14.236 mi
Registration #3	2012-03-21	19.537 mi
Registration #4	2013-03-14	23.904 mi
Registration #5	2014-03-19	27.782 mi
Registration #6	2014-03-20	27.796 mi
Registration #7	2015-03-17	30.661 mi
Registration #8	2016-03-18	34.231 mi
Registration #9	2016-03-21	34.279 mi
Registration #10	2016-03-21	35.377 mi
Registration #11	2016-03-21	35.377 mi
Registration #12	2016-03-21	35.377 mi
Registration #13	2016-03-21	35.377 mi
Registration #14	2016-03-21	35.377 mi
Registration #15	2016-03-21	35.377 mi
Registration #16	2016-03-21	35.377 mi
Registration #17	2016-03-21	35.377 mi
Registration #18	2016-03-21	35.377 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1780 mm
Height	1555 mm
Length	4839 mm
Wheel base	2750 mm
Kerb weight	1498 kg
Max. allowed weight	2132 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYVD4071845