



GM08CFU

report date: 2024-03-28

General information

Make	NISSAN
Model	ELGRAND
Colour	White
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	3.500 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-07-30
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-10
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	34
Total items failed	0

MOT #9	2023-08-11 08:15
MOT test number	885223127400
Result	✓ Passed
Next expiry date	2024-08-10
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2022-08-10 15:17
MOT test number	940903042494
Result	✓ Passed

MOT #7	2022-02-07 11:48
MOT test number	203819142932
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both tyres worn on edges (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Badly worn on inner edge.no sign of cords or ply at the of the test (5.2.3 (e))

**MOT #6** 2022-02-02 12:05**MOT test number** 712905078445**Result** ✗ Failed

- Advice** Front Tyre worn close to legal limit/worn on edge both tyres worn on edges (5.2.3 (e))
- MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- MAJOR** Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))
- Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Badly worn on inner edge.no sign of cords or ply at the of the test (5.2.3 (e))
- MAJOR** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both inner surface (1.1.14 (a) (ii))

**MOT #5** 2021-02-05 13:42**MOT test number** 274005985974**Result** ✓ Passed

- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4**

2021-02-04 15:28

**MOT test number**

315722847199

**Result****✗ Failed****Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3**

2020-02-05 14:59

**MOT test number**

397786952985

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2**

2020-02-03 10:40

**MOT test number**

403077835508

**Result****✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))



MOT #1	2019-01-09 14:35
MOT test number	161554037961
Result	✓ Passed



Tax & MOT check

✓  
Taxed

Tax due:  
1 September 2024

✓  
MOT

Expires:  
10 August 2024

Tax status		Valid until 1 September
Days left		126
MOT expiry date		10 August 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	11
First mileage registration	2008-06-20
Last registration	2023-08-11
Complete history	<a href="#">See info</a>



Registration #1	2008-06-20	23 mi
Registration #2	2019-01-09	65.466 mi
Registration #3	2020-02-03	115.826 mi
Registration #4	2020-02-05	71.986 mi
Registration #5	2021-02-04	121.943 mi
Registration #6	2021-02-05	121.948 mi
Registration #7	2023-08-11	121.948 mi
Registration #8	2023-08-11	121.948 mi
Registration #9	2023-08-11	121.948 mi
Registration #10	2023-08-11	121.948 mi
Registration #11	2023-08-11	121.948 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats 8

Engine number VQ35