



PEUGEOT



KWI2ESU

report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 HDI ALLURE
Colour	Grey
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-25
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-18
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	36
Total items failed	16

MOT #15	2024-04-19 14:56
MOT test number	626123186784
Result	✓ Passed
Next expiry date	2025-04-18
Advice	Nearside Front Body component slightly loose inner w/arch cover damaged (6.2.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Minor	Offside Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))
Advice	Electronic parking brake defective but can be satisfactorily operated switch fault (1.1.6 (d))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Body component slightly loose inner w/arch cover (6.2.1 (a) (i))
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt
Advice	O/s front daytime running lamp not working
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2024-04-19 09:22

MOT test number

692294326841

Result**✗ Failed**

- Advice** Electronic parking brake defective but can be satisfactorily operated switch fault (1.1.6 (d))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Body component slightly loose inner w/arch cover damaged (6.2.1 (a) (i))
- Advice** O/s front daytime running lamp not working
- Fail** Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))
- Advice** Offside Front Body component slightly loose inner w/arch cover (6.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13

2023-05-05 08:20

MOT test number

715112887259

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Wheel/tyre protruding beyond wheel arch
- Advice** Nearside Front Oil leak, but not excessive inner drive shaft seal (8.4.1 (a) (i))

**MOT #12**

2023-05-04 09:18

MOT test number

546711011651

Result**✗ Failed****Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Oil leak, but not excessive inner drive shaft seal (8.4.1 (a) (i))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** N/s front daytime running lamp not working**Fail** Exhaust has a major leak of exhaust gases rear silencer (6.1.2 (a))**Advice** Nearside Front Wheel/tyre protruding beyond wheel arch**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #11**

2022-04-26 14:49

MOT test number

109749029982

Result**✓ Passed****Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**MOT #10**

2022-04-26 07:57

MOT test number

649812179801

Result**✗ Failed****Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**MOT #9**

2021-05-26 08:28

MOT test number

722044211966

Result**✓ Passed**

**MOT #8** 2021-05-24 15:21**MOT test number** 885772539295**Result** ✗ Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #7 2020-07-25 09:38**MOT test number** 984354528127**Result** ✓ Passed**MOT #6** 2019-08-12 10:23**MOT test number** 978838402038**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust mounting defective (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front upper suspension top bearing stiffness in operation

MOT #5 2018-08-16 13:39**MOT test number** 836343193794**Result** ✓ Passed

**MOT #4** 2018-08-13 09:44**MOT test number** 754242387125**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corroded and worn (1.1.14 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction light on (8.2.2.2 (g))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps x2 (4.7.1 (b) (ii))**Fail** Rear Brakes imbalanced across an axle imbalance of 35% (1.2.1 (b) (i))**Pass with rectification** Front Position lamp not working both (4.2.1 (a))**Fail** Offside Parking brake inoperative on one side brake force too low (1.4.1 (a))**MOT #3** 2017-08-15 08:09**MOT test number** 270824750546**Result** ✓ Passed**MOT #2** 2016-08-10 08:02**MOT test number** 862120314933**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2015-08-17 00:00**MOT test number** 302661517744**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 3.5mm apprx (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-08-17
Last registration	2024-04-19
Complete history	See info



Registration #1	2012-08-17	29 mi
Registration #2	2015-08-17	46.923 mi
Registration #3	2016-08-10	64.897 mi
Registration #4	2017-08-15	83.257 mi
Registration #5	2018-08-13	103.963 mi
Registration #6	2018-08-16	104.098 mi
Registration #7	2019-08-12	122.837 mi
Registration #8	2020-07-25	133.841 mi
Registration #9	2021-05-24	137.326 mi
Registration #10	2022-05-22	151.377 mi
Registration #11	2022-05-22	151.377 mi
Registration #12	2022-05-22	151.377 mi
Registration #13	2022-05-22	151.377 mi
Registration #14	2022-05-22	151.377 mi
Registration #15	2022-05-22	151.377 mi
Registration #16	2022-05-22	151.377 mi
Registration #17	2022-05-22	151.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	JBER3141583