





report date: 2024-03-28

General information

Make	MINI
Model	CLUBMAN COOPER S
Colour	Black
Year of manufacture	2018
Top speed	146 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	280 Nm at 4.600 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	53.3 mpg
Consumption combined	2.8 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Date	2021-10-08
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



WK68TXY

report date: 2024-03-28

MOT history	/
-------------	---

MOT expiry date	2025-01-27
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #5	2024-01-19 13:23
MOT test number	535322144584
Result	✓ Passed
Next expiry date	2025-01-27

MOT #4	2023-01-25 14:28
MOT test number	353390459278
Result	✓ Passed

MOT #3	2022-01-28 10:34
MOT test number	169067094525
Result	✓ Passed

MOT #2	2021-09-25 11:45
--------	------------------

MOT test number 920236569787

Result		✓ Passed
Advice	Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	

CarCheck.co.uk page 3/11



Result

WK68TXY

report date: 2024-03-28

× Failed

MOT #1 2021-09-25 11:45

MOT test number 187139598421

Advice Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



WK68TXY

report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union mestery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-09-28
Last registration	2024-01-19
Complete history	See info



Registration #1	2018-09-28	22 mi
Registration #2	2021-09-25	4.761 mi
Registration #3	2021-09-25	4.761 mi
Registration #4		77,777 46
Registration #5		11.777 es
Registration #6		71,777 66
Registration #7		11,777 mi

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1200 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	44	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4	page 11/11

Number of axles 2

Engine number F409H882