



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Blue
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





## MOT history

MOT expiry date	2024-08-13
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	26
Total items failed	3

MOT #13	2023-08-08 13:53
MOT test number	403497772070
Result	✓ Passed
Next expiry date	2024-08-13

MOT #12	2022-08-11 14:25
MOT test number	507543226251
Result	✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11	2022-08-11 09:02
MOT test number	999345159617
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10** 2021-08-14 11:35**MOT test number** 303042350338**Result** ✓ Passed**MOT #9** 2020-08-11 11:54**MOT test number** 931602755495**Result** ✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Nail in tyre
- Minor** Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Rear axle corroded
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #8** 2019-08-09 13:40**MOT test number** 457163580001**Result** ✓ Passed

- Advice** Both rear discs corroded slightly
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Rear exhaust deteriorated slightly
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))

**MOT #7** 2019-08-09 13:40**MOT test number** 894468208654**Result** ✗ Failed**Advice** Both rear discs corroded slightly**Advice** Offside Side repeater slightly discoloured (4.4.3 (a))**Advice** Rear exhaust deteriorated slightly**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Pass with rectification** Nearside Front Position lamp not working dip beam (4.2.1 (a) (ii))**MOT #6** 2018-08-07 15:36**MOT test number** 682934236298**Result** ✓ Passed**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #5** 2017-08-10 13:26**MOT test number** 947059917443**Result** ✓ Passed**Advice** Both rear discs corroded slightly**MOT #4** 2016-08-08 08:49**MOT test number** 978108813906**Result** ✓ Passed**MOT #3** 2015-08-10 16:25**MOT test number** 368852125422**Result** ✓ Passed**Advice** Offside Front Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)



MOT #2	2014-07-28 12:54
MOT test number	317369604429
Result	✓ Passed

MOT #1	2013-07-31 14:36
MOT test number	895182413270
Result	✓ Passed

**Notice** Surface corrosion on brake discs



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
13 August 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	368
<b>MOT expiry date</b>	13 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-03-12
Last registration	2023-08-08
Complete history	<a href="#">See info</a>



Registration #1	2010-03-12	15 mi
Registration #2	2013-07-31	4.453 mi
Registration #3	2014-07-28	13.573 mi
Registration #4	2015-08-10	20.373 mi
Registration #5	2016-08-08	25.691 mi
Registration #6	2017-08-10	32.912 mi
Registration #7	2018-08-07	38.338 mi
Registration #8	2019-08-07	43.764 mi
Registration #9	2020-08-07	49.190 mi
Registration #10	2021-08-07	54.616 mi
Registration #11	2022-08-07	60.042 mi
Registration #12	2023-08-08	65.468 mi
Registration #13	2024-03-28	70.894 mi
Registration #14	2024-03-28	76.320 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1070 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CGG0405070